

App. B:
Petrie Decl., Ex. 2
Part III

Confidential

12150	700	N/A	3006 SPRG	12-Mar-76	N	S	10-Jul-15	10-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501409	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12148	700	84364	308 WIN	2-Jan-13	N	S	10-Jul-15	10-Jul-15	Fired on Safe Release	Could Not Duplicate Concern	501318	F	Per Ilion - Replace TA & test @ n/c
12142	700	25803	7MM REM MA	20-Jan-03	N	S	10-Jul-15	10-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501355	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12157	700	84370	223 REM	20-Apr-09	N	S	14-Jul-15	14-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501431	F	Per Ilion - Repair at n/c, XMP update
12159	700	29717	3006 SPRG	24-Feb-03	N	S	14-Jul-15	14-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501456	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12158	700	N/A	308 WIN	15-Jun-81	N	S	14-Jul-15	14-Jul-15	Fired With Safe ON	Improper Maintenance	501476	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12156	887	82500	12 GA	13-Nov-13	N	S	14-Jul-15	14-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501426	F	Per Ilion - Repair at n/c
12154	Para RECON 9	96699	9MM	7-Jan-15	N	S	14-Jul-15	14-Jul-15	Fired Out of Battery	Could Not Duplicate Concern	501472	F	Per Ilion - Repair at n/c
12170	700	not avail.	17 REM	4-May-72	N	S	16-Jul-15	16-Jul-15	Fired on Bolt Closing	Altered Adjustments or Components	501624	F	Per Ilion - Repair at n/c
12167	700	27119	243 WIN	2-Nov-11	N	S	16-Jul-15	16-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501563	F	Per Ilion - Repair at n/c, XMP update
12171	700	not avail.	270 WIN	19-Apr-80	N	S	16-Jul-15	16-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501562	F	Per Ilion - Repair at n/c
12164	700	29717	3006 SPRG	3-Mar-93	N	S	16-Jul-15	16-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501561	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12165	700	N/A	3006 SPRG	3-Jun-80	N	S	16-Jul-15	16-Jul-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	501625	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12169	700	N/A	3006 SPRG	8-Dec-70	N	S	16-Jul-15	16-Jul-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	501622	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12175	700	84218	308 WIN	21-Nov-12	N	PI/S	16-Jul-15	*	Fired on Bolt Closing	Other - Unexamined		F	
12179	CARBON 15	90806	223/5.56	1-May-13	N	PD/S	17-Jul-15	*	Unexplained Discharge - No Mention of Safety Position	Other - Unexamined		F	
12186	700	85334	243 WIN	28-Aug-13	N	S	20-Jul-15	20-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501688	F	Per Ilion - Repair at n/c
12184	700	25849	25-06 REM	15-Jun-98	N	S	20-Jul-15	20-Jul-15	Other - Firearms - XMP Update	Sent in for Evaluation	501687	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12183	700	29711	280 REM	16-Oct-92	N	S	20-Jul-15	20-Jul-15	Other - Firearms - XMP Update	Could Not Duplicate Concern	501690	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge

RAC001235

Confidential

12182	700	60201	3006 SPRG	1-Jul-65	N	S	20-Jul-15	20-Jul-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	501650	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12185	700	N/A	3006 SPRG	17-Sep-81	N	S	20-Jul-15	20-Jul-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	501689	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12187	700	not avail.	7MM REM MA	27-Feb-80	N	S	20-Jul-15	20-Jul-15	Other- Firearms - XMP Update	Could Not Duplicate Concern	501686	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12188	700	not avail.	7MM REM MA	2-Apr-80	N	S	20-Jul-15	20-Jul-15	Other- Does not trust firearm	Could Not Duplicate Concern	501685	F	Per Ilion - Repair at n/c
12181	700 ML	27572	50 CAL	28-Sep-96	N	S	20-Jul-15	20-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501684	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12193	597	26516	17 HMR	31-Jan-03	N	PI/PD/S	20-Jul-15	19-Aug-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	502587	F	Replace with Ramac 70701 in exchange
12197	660	not avail.	243 WIN	1-Feb-68	Y	S	22-Jul-15	22-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501872	F	Per Ilion - Repair at n/c
12205	673	24687	350 REM MA	18-Jun-03	N	S	22-Jul-15	22-Jul-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	501792	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12198	700	N/A	22-250 REM	14-Feb-81	N	S	22-Jul-15	22-Jul-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	501796	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12201	700	not avail.	243 WIN	5-May-71	N	S	22-Jul-15	22-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501794	F	Per Ilion - Repair at n/c
12195	700	N/A	270 WIN	24-Sep-71	N	S	22-Jul-15	22-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501790	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12199	700	not avail.	3006 SPRG	29-Apr-74	N	S	22-Jul-15	22-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501791	F	Per Ilion - Repair at n/c
12204	700	N/A	3006 SPRG	3-Feb-72	N	S	22-Jul-15	22-Jul-15	Fired on Safe Release	Altered Adjustments or Components	501789	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12200	887	82500	12 GA	7-Jul-09	N	S	22-Jul-15	22-Jul-15	Fired Out of Battery	Sent in for Evaluation	501815	F	Per Ilion, check over completely, repair as needed, and test at no charge.
12203	700	20000	7MM MAG		N	PD/S	22-Jul-15	7-Aug-15	Unexplained Discharge - No Mention of Safety Position	Other - Unexamined	n/a	F	No further contact from customer
12206	710	27410	3006 SPRG	9-Aug-06	Y	S	22-Jul-15	6-Aug-15	Fired on Bolt Closing	Could Not Duplicate Concern	501793	F	Replace w/85846 in exchange
12214	700	27476	270 WIN	19-Aug-95	N	PD/S	24-Jul-15	24-Jul-15	Delayed Firing - Firearms	Could Not Duplicate Concern	501930	F	Per Ilion - Repair at n/c
12213	700	84401	25-06 REM	16-Feb-09	N	S	24-Jul-15	24-Jul-15	Other- Firearms - XMP Update	Could Not Duplicate Concern	501928	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12211	700	N/A	270 WIN	22-Jul-74	N	S	24-Jul-15	24-Jul-15	Fired on Bolt Opening	Improper Maintenance	501931	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge

RAC001236

Confidential

12216	700	not avail.	270 WIN	19-May-69	N	S	24-Jul-15	24-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501932	F	Per Ilion - Repair at n/c
12218	700	not avail.	3006 SPRG	13-Aug-75	N	S	24-Jul-15	24-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501934	F	Per Ilion - Repair at n/c
12220	700	27095	3006 SPRG	6-Sep-07	N	S	24-Jul-15	24-Jul-15	Other- Firearms - XMP Update	Could Not Duplicate Concern	501927	F	Per Ilion - Repair at n/c, XMP update
12210	700	N/A	308 WIN	1-Feb-84	N	S	24-Jul-15	24-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501929	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12219	700	not avail.	7MM REM MA	21-Sep-76	N	S	24-Jul-15	24-Jul-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	501933	F	Per Ilion - Repair at n/c
12215	887	82501	12 GA	2-Mar-10	N	S	24-Jul-15	24-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501902	F	Per Ilion, check over completely, repair as needed, and test at no charge.
12212	710	27410	3006 SPRG	29-Jul-03	Y	S	24-Jul-15	18-Sep-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	501925	F	Replace with Ramac 85846 in exchange
12222	700	N/A	3006 SPRG	25-Aug-78	N	S	28-Jul-15	28-Jul-15	Fired on Safe Release	Altered Adjustments or Components	501970	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12223	700	84207	308 WIN	17-Mar-12	N	S	28-Jul-15	28-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502001	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12238	770	85657	7MM REM MA	1-Mar-10	Y	S	28-Jul-15	19-Aug-15	Other - Firearms	Altered Adjustments or Components	502026	F	Replace with Ramac 85848 in exchange
12227	597	26516	17 HMR	4-May-06	N	S	28-Jul-15	28-Jul-15	Other - Firearms	Sent in for Evaluation	502013	F	70701
12235	700	27512	22-250 REM	23-Jul-99	N	S	28-Jul-15	28-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	502032	F	Per Ilion - Repair at n/c
12236	700	25825	223 REM	16-Feb-89	N	S	28-Jul-15	28-Jul-15	Delayed Firing - Firearms	Could Not Duplicate Concern	502034	F	Per Ilion - Repair at n/c
12234	700	27119	243 WIN	28-Feb-06	N	PI/S	28-Jul-15	28-Jul-15	Fired on Safe Release	Could Not Duplicate Concern	502039	F	Per Ilion - Repair at n/c
12230	700	N/A	270 WIN	20-Aug-79	N	S	28-Jul-15	28-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502038	F	Per Ilion, replace trigger assembly, check over at no charge
12233	700	25864	270 WIN	12-Jan-84	N	S	28-Jul-15	28-Jul-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	502035	F	Per Ilion - Repair at n/c
12228	700	85338	300 WIN MA	25-Oct-12	N	S	28-Jul-15	28-Jul-15	Other - Firearms - XMP Update	Sent in for Evaluation	502000	F	Per Ilion - Repair at n/c, XMP update, Cr for \$20.51 for shipping refund
12224	700	25773	3006 SPRG	21-Jul-88	N	S	28-Jul-15	28-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502030	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12231	700	not avail.	3006 SPRG	20-Mar-80	N	S	28-Jul-15	28-Jul-15	Fired on Safe Release	Sent in for Evaluation	502040	F	Per Ilion - Repair at n/c

RAC001237

Confidential

12232	700	not avail.	3006 SPRG	4-Jun-74	N	S	28-Jul-15	28-Jul-15	Unexplained Discharge Safe OFF	Altered Adjustments or Components	502033	F	Per Iliion - Repair at n/c
12229	700	27572	50 CAL	28-May-96	N	S	28-Jul-15	28-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502036	F	Per Iliion, replace trigger assembly, check over at no charge
12225	700	N/A	6MM REM	21-Mar-69	N	S	28-Jul-15	28-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501999	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge
12237	700	not avail.	7MM REM MA	12-Jul-79	N	S	28-Jul-15	28-Jul-15	Fired With Safe ON	Altered Adjustments or Components	502037	F	Per Iliion - Repair at n/c
12226	SEVEN	N/A	6MM REM	1-Jul-83	N	S	28-Jul-15	28-Jul-15	Fired on Safe Release	Could Not Duplicate Concern	502031	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge
12254	700	25714	223 REM	26-Feb-15	N	S	4-Aug-15	4-Aug-15	Fired on Bolt Closing	Could Not Duplicate Concern	502159	F	Per Iliion - Repair at n/c
12260	700	not avail.	223 REM	22-Dec-76	N	S	4-Aug-15	19-Aug-15	Fired on Safe Release	Altered Adjustments or Components	502144	F	Per Iliion - Repair at n/c
12256	700	85335	270 WIN	2-Oct-12	N	S	4-Aug-15	26-Aug-15	Fired on Bolt Closing	Could Not Duplicate Concern	502140	F	Per Iliion - Repair at n/c, XMP update
12258	700	27121	270 WIN	10-May-12	N	S	4-Aug-15	4-Aug-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502141	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge
12257	700	25632	280 REM	17-Apr-87	N	S	4-Aug-15	26-Aug-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	502084	F	Per Iliion - Repair at n/c
12251	700	85367	300 RUM	21-Apr-07	N	S	4-Aug-15	4-Aug-15	Other - Firearms - XMP Update	Altered Adjustments or Components	502110	F	Per Iliion - Repair at n/c, XMP update
12252	700	25634	3006 SPRG	16-Mar-89	N	S	4-Aug-15	27-Aug-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502146	F	Per Iliion - Repair at n/c
12255	700	not avail.	3006 SPRG	19-Jan-88	N	S	4-Aug-15	21-Aug-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	502142	F	Per Iliion - Repair at n/c
12262	700	not avail.	3006 SPRG	15-May-81	N	S	4-Aug-15	19-Aug-15	Unexplained Discharge Safe ON	Sent in for Evaluation	502143	F	Per Iliion - Repair at n/c
12250	700	27499	308 WIN	23-Feb-01	N	S	4-Aug-15	21-Aug-15	Fired on Safe Release	Could Not Duplicate Concern	502112	F	Per Iliion - Repair at n/c
12253	700	not avail.	308 WIN	18-Jan-72	N	S	4-Aug-15	4-Aug-15	Other - Firearms - XMP Update	Sent in for Evaluation	502111	F	Per Iliion - Repair at n/c, XMP update
12261	770	85632	270 WIN	15-Jul-08	Y	S	4-Aug-15	4-Aug-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	502145	F	Consumer Service replaced with Ramac 85844 in exchange
12267	700	29703	223 REM	23-Feb-01	N	S	5-Aug-15	22-Aug-15	Fired on Bolt Closing	Could Not Duplicate Concern	502254	F	Per Iliion - Repair at n/c, XMP update
12274	700	N/A	3006 SPRG	1-Nov-66	N	S	5-Aug-15	5-Aug-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	502210	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge
12275	700	25793	3006 SPRG	27-Aug-86	N	S	5-Aug-15	5-Aug-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502253	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge

RAC001238

Confidential

12279	597	26516	17 HMR	10-Jul-05	N	PD/S	6-Aug-15	1-Sep-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	503099	F	Replace with Ramac 70712 in exchange
12615	M-4	n/a	223		N	S/C	6-Aug-15	30-Oct-15	Barrel Damaged/Bulged (Other than Burst)	Other - Unspecified or Undetermined - Ammunition	n/a	A	Lonoke to replace ammunition to Fleet for return SNC\$2,890.71
12282	700	84215	223 REM	9-Mar-10	N	S	10-Aug-15	28-Aug-15	Unexplained Discharge - No Mention of Safety Position	AFT MKT TRIGGER ASSM	502401	F	Per lliion - Repair at n/c - goodwill
12287	700	not avail.	270 WIN	17-Nov-81	N	S	10-Aug-15	31-Aug-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502402	F	Per lliion- repair at no charge
12281	700	not avail.	7MM REM MA	1-Jun-62	N	S	10-Aug-15	28-Aug-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502404	F	Per lliion - Repair at n/c
12291	710	27410	3006 SPRG	9-Dec-03	Y	S	10-Aug-15	10-Aug-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502354	F	Replace with Ramac 85846 in exchange
12289	700	not avail.	3006 SPRG	24-Aug-76	N	PI/S	10-Aug-15	3-Sep-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	502347	F	Per lliion- Repair at no charge
12285	700	not avail.	25-06 REM	3-Feb-71	N	S	10-Aug-15	1-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502352	F	Per lliion- repair at no charge
12284	700	not avail.	300 WIN MA	8-Apr-80	N	S	10-Aug-15	1-Sep-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	502351	F	Per lliion- repair at n/c
12283	770	85635	7MM REM MA	26-Aug-08	Y	S	10-Aug-15	9-Sep-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	502353	F	Replace w/85848 in exchange through SNC order
12286	SPORTSMAN 78	26172	223 REM	20-Mar-89	Y	S	10-Aug-15	11-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502403	F	Per lliion- repair at no charge
12310	Rossi single shot	n/a	22 LR		N	PI/S	11-Aug-15	20-Aug-15	Ammunition Exploded	Other - Unspecified or Undetermined - Ammunition	n/a	A	Lonoke - replaced ammo
12296	1187	29879	12 GA	8-Aug-12	N	S	12-Aug-15	*	Unexplained Discharge Safe OFF	Other - Unexamined		F	
12301	700	25818	308 WIN	11-Aug-89	N	S	13-Aug-15	13-Aug-15	Fired on Safe Release	Could Not Duplicate Concern	502445	F	Per lliion- repair at n/c
12303	750	27057	308 WIN	20-Feb-14	N	S	13-Aug-15	13-Aug-15	Fired on Bolt Closing	Could Not Duplicate Concern	502416	F	Per lliion- Check over completely
12302	887	82500	12 GA	23-Jun-14	N	S	13-Aug-15	13-Aug-15	Fired on Bolt Closing	Sent in for Evaluation	502420	F	Per lliion-repair as needed at n/c
12300	700	not avail.	243 WIN	29-Jan-73	N	S	13-Aug-15	1-Sep-15	Other- Firearms - XMP Update	Could Not Duplicate Concern	502447	F	Per lliion- repair at n/c
12299	700	not avail.	3006 SPRG	24-May-73	N	S	13-Aug-15	1-Sep-15	Other- Firearms - XMP Update	Could Not Duplicate Concern	502446	F	Per lliion- repair at n/c

RAC001239

Confidential

12309	700	not avail.			N	PD/S	14-Aug-15	19-Feb-16	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	n/a	Rifle not returned to Ilion for exam
12316	700	not avail.	3006 SPRG	20-Feb-79	N	S	17-Aug-15	17-Aug-15	Fired on Bolt Closing	Could Not Duplicate Concern	502543	F Per Ilion- repair at n/c
12314	700	84207	308 WIN	17-Jun-13	N	S	17-Aug-15	17-Aug-15	Fired With Safe ON	Could Not Duplicate Concern	502542	F Per Ilion- repair at n/c
12317	700	25739	308 WIN	3-May-10	N	S	17-Aug-15	17-Aug-15	Fired on Safe Release	Could Not Duplicate Concern	502449	F Per Ilion- repair at n/c
12315	700	not avail.	300 WIN MA	1-Sep-67	N	S	17-Aug-15	3-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502544	F Per Ilion- repair at no charge
12324	700	not avail.	3006 SPRG	10-Jun-78	N	S	19-Aug-15	19-Aug-15	Fired on Safe Release	Could Not Duplicate Concern	502630	F Per Ilion- Repair at no charge
12325	700	25715	308 WIN	15-Nov-99	N	S	19-Aug-15	26-Aug-15	Fired on Bolt Closing	Could Not Duplicate Concern	502631	F Per Ilion-repair at n/c
12322	770	85649	243 WIN	20-Sep-12	Y	S	19-Aug-15	19-Aug-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	502591	Consumer Service replaced with Ramac 85842 in exchange
12326	700	not avail.	270 WIN	2-Feb-79	N	PD/S	19-Aug-15	2-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502590	F Per Ilion- repair at n/c
12320	SEVEN	24741	7MM-08 REM	12-Jul-02	N	S	19-Aug-15	1-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	502689	F Per Ilion- Repair at no charge
12342	700	84020	257 ROBERT	10-Aug-09	N	S	24-Aug-15	24-Aug-15	Other- Firearms - XMP Update	Could Not Duplicate Concern	502802	F Per Ilion- Replace TA and test
12347	700	not avail.	280 REM	1-Jul-66	N	S	24-Aug-15	31-Aug-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	502756	F Per Ilion- Repair as needed
12343	700	26129	3006 SPRG	21-Oct-98	N	S	24-Aug-15	31-Aug-15	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	502805	F Per Ilion- Replace TA and test
12340	770	85633	3006 SPRG	22-Jul-11	Y	S	24-Aug-15	24-Aug-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502803	Replace with Ramac 85846 in exchange
12344	770	85633	3006 SPRG	3-Jan-14	Y	S	24-Aug-15	24-Aug-15	Fired on Safe Release	Could Not Duplicate Concern	502712	Replace with Ramac 85846 in exchange
12341	700	not avail.	222 REM	1-Feb-64	N	S	24-Aug-15	2-Sep-15	Fired on Bolt Opening	Could Not Duplicate Concern	502757	F Per Ilion- Repair TA and test
12339	700	not avail.	270 WIN	5-Oct-72	N	S	24-Aug-15	3-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	502804	F Per Ilion- Repair as needed
12335	ACR	90838	223/5.56	24-Sep-13	N	S	24-Aug-15	24-Aug-15	Went Automatic	Could Not Duplicate Concern	502811	F Per Ilion- Check over completely
12337	ACR	90838	223/5.56	1-Feb-13	N	S	24-Aug-15	24-Aug-15	Went Automatic	Sent in for Evaluation	502761	F Per Ilion- Check over completely and repair as needed
12362	700	not avail.	243 WIN	20-Nov-75	N	PD/S	25-Aug-15	31-Aug-15	Unexplained Discharge Safe ON	Could Not Duplicate Concern	502915	F Per Ilion- Replace TA and test
12351	700	27269	3006 SPRG	7-Jan-14	N	S	25-Aug-15	25-Aug-15	Fired on Bolt Closing	Could Not Duplicate Concern	502862	F Per Ilion- Replace TA and test
12358	700	not avail.	3006 SPRG	14-Jan-75	N	S	25-Aug-15	31-Aug-15	Other- Firearms - XMP Update	Could Not Duplicate Concern	502910	F Per Ilion- Replace TA and test
12361	700	not avail.	3006 SPRG	18-Aug-80	N	S	25-Aug-15	25-Aug-15	Fired With Safe ON	Could Not Duplicate Concern	502913	F Per Ilion- Replace TA and test
12355	710	27414	300 WIN MA	18-Jul-05	Y	S	25-Aug-15	25-Aug-15	Fired on Bolt Closing	Altered Adjustments or Components	502861	Per Ilion-Replace with 783 at N/C

RAC001240

Confidential

12364	770	85634	308 WIN	12-Nov-12	Y	S	25-Aug-15	25-Aug-15	Excessive Headspace	Could Not Duplicate Concern	502918	F	Per Ilion- Repair as needed
12356	700	not avail.	25-06 REM	14-Jul-78	N	PD/S	25-Aug-15	3-Sep-15	Fired on Bolt Closing	Could Not Duplicate Concern	502914	F	Per Ilion- Replace TA and test
12353	700	not avail.	22-250 REM	12-Jul-77	N	PI/S	25-Aug-15	8-Sep-15	Other- Firearms - XMP Update	Could Not Duplicate Concern	502912	F	Per Ilion- Replace TA and test
12359	700	not avail.	270 WIN	5-May-80	N	S	25-Aug-15	11-Sep-15	Fired on Safe Release	Altered Adjustments or Components	502916	F	Per Ilion- Replace TA and test
12352	700	26098	3006 SPRG	8-May-92	N	S	25-Aug-15	8-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	502908	F	Per Ilion- Replace TA and test
12360	700	25859	3006 SPRG	24-Apr-00	N	S	25-Aug-15	1-Sep-15	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	502909	F	Per Ilion- Repair as needed
12357	700 ML	27580	50 CAL	10-Jul-96	N	S	25-Aug-15	8-Sep-15	Other- Firearms - XMP Update	Could Not Duplicate Concern	502911	F	Per Ilion- Replace TA and test
12370	700	27357	7MM-08 REM	27-Jan-14	N	S	27-Aug-15	15-Sep-15	Fired on Bolt Closing	Could Not Duplicate Concern	503660	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12374	700	25789	25-06 REM	13-Mar-87	N	S	28-Aug-15	28-Aug-15	Delayed Firing - Firearms	Could Not Duplicate Concern	503014	F	Per Ilion- Replace TA and test
12380	700	27099	300 WIN	19-Mar-13	N	S	28-Aug-15	28-Aug-15	Other- Firearms - XMP Update	Could Not Duplicate Concern	503060	F	Per Ilion- Replace TA and test
12375	700	86463	308 WIN	11-Dec-14	N	S	28-Aug-15	28-Aug-15	Fired on Safe Release	Sent in for Evaluation	503056	F	Per Ilion- Replace TA and test
12381	700	27474	243 WIN	5-Jun-02	N	PI/PD/S	28-Aug-15	9-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	503068	F	Per Ilion- Replace TA and test
12376	700	25791	270 WIN	24-Aug-90	N	S	28-Aug-15	11-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503067	F	Per Ilion- Replace TA and test
12377	700	26010	300 RUM	2-Feb-04	N	S	28-Aug-15	11-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503066	F	Per Ilion- Replace TA and test
12379	700	not avail.	3006 SPRG	7-Oct-70	N	S	28-Aug-15	3-Sep-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	503059	F	Per Ilion- Replace TA and test
12378	SPORTSMAN 78	26164	3006 SPRG	17-Jul-87	Y	S	28-Aug-15	8-Sep-15	Fired on Safe Release	Altered Adjustments or Components	503061	F	Per Ilion- Replace TA and test
12387	870	25098	12 GA	19-Jul-13	N	PD/S	31-Aug-15	24-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504037	F	Per Ilion- Check over completely
12392	770	85634	308 WIN	14-Feb-14	Y	PD/S	1-Sep-15	1-Sep-15	Broken Part	Sent in for Evaluation	503171	F	Per Ilion- Check over completely and repair as needed
12394	700	25600	ROBERT 257	2-May-91	N	S	1-Sep-15	1-Sep-15	Fired on Bolt Closing	Could Not Duplicate Concern	503098	F	Per Ilion- Replace TA and test
12393	H&R PARDNER	72282	20 GA	3-May-14	N	S	1-Sep-15	1-Sep-15	Fired With Safe ON	Sent in for Evaluation	503125	F	Per Ilion- Repair or replace as needed
12390	CARBON 15	90689	223/5.56	16-May-13	N	S	1-Sep-15	1-Sep-15	Fired With Safe ON	Sent in for Evaluation	503186	F	Per Ilion- Check over completely and repair as needed
12389	XM15-E2S	not avail.	223/5.56	28-Sep-06	N	S	1-Sep-15	1-Sep-15	Receiver Damaged	Over pressured shell	503185	F	Per Ilion- Replace at 1/2 cost Consumer Service replacing in exchange with Ramac
12401	597	80875	22 LR	23-Dec-13	N	PD/S	3-Sep-15	3-Sep-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	503212	F	80877.

RAC001241

Confidential

12407	700	27094	270 WIN	8-Aug-07	N	PD/S	3-Sep-15	18-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503225	F	Repair @ n/c under XMP recall
12404	870	25571	12 GA	6-Feb-89	N	PD/S	3-Sep-15	14-Sep-15	Fired With Safe ON	Fired from Contact with Foreign Object	503213	F	Per Ilion- Replace firearm at 1/2 cost
12405	870	25571	12 GA	6-Feb-89	N	PD/S	3-Sep-15	3-Sep-15	Fired With Safe ON	Could Not Duplicate Concern	503215	F	Per Ilion- Check over completely and repair as needed
12402	700	27269	3006 SPRG	12-Aug-05	N	PI/S	3-Sep-15	3-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503224	F	Repair @ n/c
12408	700	not avail.	243 WIN	23-Jan-73	N	S	3-Sep-15	3-Sep-15	Other - Firearms	Altered Adjustments or Components	503216	F	Per Ilion- Replace TA and test
12409	700	not avail.	7MM REM	24-May-76	N	S	3-Sep-15	3-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	503251	F	Per Ilion- Replace TA and test
12406	721	not avail.	3006 SPRG	1-Aug-69	Y	S	3-Sep-15	22-Sep-15	Fired on Bolt Closing	Sent in for Evaluation	503267	F	Per Ilion- Replace TA and test
12400	870	25571	12 GA	6-Feb-89	N	S	3-Sep-15	3-Sep-15	Fired With Safe ON	Could Not Duplicate Concern	503214	F	Per Ilion- Check over completely and repair as needed
12399	887	82500	12 GA	15-Feb-10	N	S	3-Sep-15	3-Sep-15	Fail to Fire	Could Not Duplicate Concern	503237	F	Per Ilion- Check over completely and repair as needed
12416	597	26516	17 HMR	15-Oct-03	N	PD/S	9-Sep-15	9-Sep-15	My Gun Blew Up	Could Not Duplicate Concern	503395	F	Call center issued refund Per Ilion- Check over completely and repair as needed
12422	870	25077	12 GA	14-May-13	N	PD/S	9-Sep-15	9-Sep-15	My Gun Blew Up	Could Not Duplicate Concern	503346	F	Per Ilion- Check over completely and repair as needed
12414	R-15	60005	223 REM	25-Nov-08	N	PD/S	9-Sep-15	9-Sep-15	My Gun Blew Up	Over pressured shell	503357	F	Returned as Received as requested by customer
12415	700	not avail.	270 WIN	19-Sep-84	N	PI/S	9-Sep-15	16-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	503367	F	Repair @ n/c
12418	700	not avail.	243 WIN	15-Feb-71	N	S	9-Sep-15	29-Sep-15	Fired on Bolt Opening	Could Not Duplicate Concern	503419	F	Per Ilion- Replace TA and test
12419	700	not avail.	243 WIN	15-Oct-77	N	S	9-Sep-15	24-Sep-15	Other - Firearms - XMP Update	Could Not Duplicate Concern	503977	F	Per Ilion - Replace TA & test @ n/c
12417	700	84014	270 WIN	6-Jun-13	N	S	9-Sep-15	9-Sep-15	Other - Firearms - XMP Update	Could Not Duplicate Concern	503451	F	Per Ilion- Replace TA and test
12420	700	not avail.	3006 SPRG	7-May-74	N	S	9-Sep-15	29-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503421	F	Per Ilion- Replace TA and test
12421	SEVEN	24741	7MM-08 REM	22-Jul-97	N	S	9-Sep-15	16-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503450	F	Per Ilion- Replace TA and test
12424	Para Expert	96745	45 AUTO	11-Dec-14	N	S	10-Sep-15	16-Nov-15	Fired Out of Battery	Sent in for Evaluation	504208	F	Per Release - Replace w/96323 in exchange
12425	887	82500	12 GA	7-Oct-09	N	PD/S	11-Sep-15	2-Nov-15	Fired on Bolt Closing	Could Not Duplicate Concern	504558	F	Check over, repair if needed & test @ n/c - goodwill
12434	597	26513	22 LR	19-Mar-13	N	PD/S	14-Sep-15	14-Sep-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	503516	F	Per Ilion- Check over completely and repair as needed
12429	700	not avail.	270 WIN	24-Apr-80	N	S	14-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503537	F	Per Ilion- Replace TA and test

RAC001242

Confidential

12436	700	not avail.	270 WIN	20-Jul-78	N	S	14-Sep-15	14-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	503473	F	Per Ilion- Replace TA and test
12428	700	not avail.	3006 SPRG	5-Mar-80	N	S	14-Sep-15	14-Sep-15	Fired on Bolt Closing	Could Not Duplicate Concern	503539	F	Per Ilion- Replace TA and test
12432	700	25793	3006 SPRG	8-Dec-82	N	S	14-Sep-15	30-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	503540	F	Per Ilion- Replace TA and test
12433	700	not avail.	3006 SPRG	1-Apr-72	N	S	14-Sep-15	14-Sep-15	Fired on Safe Release	Improper Maintenance	503501	F	Per Ilion- Replace TA and test
12435	700	not avail.	3006 SPRG	16-Jul-73	N	S	14-Sep-15	14-Sep-15	Fired on Safe Release	Altered Adjustments or Components	503496	F	Per Ilion- Replace TA and test
12430	700	27523	308 WIN	10-May-00	N	S	14-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	503568	F	Per Ilion- Replace TA and test
12431	870	25568	12 GA	10-Mar-14	N	S	14-Sep-15	14-Sep-15	Fail to Fire	Could Not Duplicate Concern	503536	F	Per Ilion- Check over completely and repair as needed
12427	DPMS G2 HUNTER	60238	7.62 X51	7-Apr-15	N	PD/S	14-Sep-15	6-Oct-15	Fired Out of Battery	Over pressured shell	503586	F	Per Ilion- Replace w/60238 in exchange
12438	887	82500	12 GA	19-Jun-13	N	PI/S	14-Sep-15	*	Fired With Safe ON	Other - Unexamined		F	
12440	700	27514	223 REM	21-Jul-99	N	S	15-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503642	F	Per Ilion- Replace TA and test
12439	700	85435	243 WIN	18-May-12	N	S	15-Sep-15	15-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	503634	F	Per Ilion- Replace TA and test
12441	700	not avail.	243 WIN	25-Mar-69	N	S	15-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	503675	F	Per Ilion- Replace TA and test
12442	700	not avail.	270 WIN	8-Jan-85	N	S	15-Sep-15	15-Sep-15	Fired on Bolt Closing	Improper Maintenance	503676	F	Per Ilion- Replace TA and test
12443	700	25774	308 WIN	15-Feb-83	N	S	15-Sep-15	15-Oct-15	Other - Does not trust firearm	Could Not Duplicate Concern	503643	F	Per Ilion- Replace TA and test
12444	SEVEN	24741	7MM-08 REM	29-Mar-95	N	S	15-Sep-15	15-Oct-15	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	503700	F	Per Ilion- Replace TA and test
12448	597	26513	22 LR	7-Dec-12	N	PD/S	17-Sep-15	17-Sep-15	Receiver Damaged	Other - Unspecified or Undetermined - Ammunition	503763	F	Per Ilion- Repair as needed
12446	700 ML	27572	50 CAL	28-Apr-97	N	PI/S	17-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503761	F	Per Ilion- Replace TA and test
12447	700	not avail.	243 WIN	3-Jun-76	N	S	17-Sep-15	17-Sep-15	Fired on Safe Release	Altered Adjustments or Components	503777	F	Per Ilion- Replace TA and test
12445	887	82500	12 GA	17-Dec-13	N	S	17-Sep-15	17-Sep-15	Fired on Bolt Closing	Could Not Duplicate Concern	503760	F	Per Ilion- Check over completely and repair as needed
12454	700	not avail.	270 WIN	17-Aug-79	N	S	21-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503810	F	Per Ilion- Replace TA and test
12452	700	25773	3006 SPRG	5-Jan-02	N	S	21-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503809	F	Per Ilion- Replace TA and test
12451	1100	25332	12 GA	18-Jul-77	N	S	21-Sep-15	21-Sep-15	My Gun Blew Up	Sent in for Evaluation	503914	F	Per Ilion- Quote to repair or replace

RAC001243

Confidential

12459	700 ML	27580	50 CAL	24-Jul-96	N	S	21-Sep-15	30-Sep-15	Fired on Bolt Closing	Could Not Duplicate Concern	503913	F	Per Ilion- Replace TA and test
12458	700	26352	8MM MAUSER	11-Nov-03	N	S	21-Sep-15	1-Oct-15	Fired on Bolt Closing	Could Not Duplicate Concern	503912	F	Per Ilion- Replace TA and test
12453	710	27410	3006 SPRG	12-Apr-01	Y	S	21-Sep-15	13-Oct-15	Fired on Safe Release	Sent in for Evaluation	503924	F	Per Ilion-Replace with 783 in exchange
12464	CARBON 15	90689	223/5.56	11-Mar-13	N	S	22-Sep-15	22-Sep-15	Case Failure	Over pressured shell	503834	F	Per Ilion- Replace at 1/2 cost
12469	547	87971	17 HMR	4-Feb-15	N	S	24-Sep-15	24-Sep-15	Ammunition Exploded	Sent in for Evaluation	503986	F	Per Ilion- Repair as needed
12470	700	26965	3006 SPRG	7-Dec-95	N	S	24-Sep-15	24-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	504015	F	Per Ilion- Replace TA and test
12466	870	25098	12 GA	15-Dec-11	N	S	24-Sep-15	24-Sep-15	Fired Out of Battery	Fired from Contact with Foreign Object	504036	F	Per Ilion- Check over completely and repair as needed at no charge
12468	597	26513	22 LR	20-May-15	N	PD/S	24-Sep-15	19-Nov-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	504014	F	Per Ilion- Check over completely and repair as needed . Lonoke sending ammunition (13.91
12472	DPMS A-15	N/A	223/5.56	1-Jan-15	N	S	24-Sep-15	24-Sep-15	Failed to Extract	Could Not Duplicate Concern	503930	F	Per Ilion, check over completely, repair as needed, and test at no charge
12480	870	25098	12 GA	9-May-11	N	PD/S	28-Sep-15	28-Sep-15	Fired Out of Battery	Fired from Contact with Foreign Object	504107	F	Check over completely, repair as needed, and test at no charge
12484	710	27408	270 WIN	19-Nov-04	Y	S	28-Sep-15	28-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504038	F	Replace with Ramac 85844 in exchange
12476	887	82500	12 GA	10-May-13	N	S	28-Sep-15	28-Sep-15	Jamming/Feeding issues	Could Not Duplicate Concern	504068	F	Per Ilion- Check over completely and repair as needed
12477	7400	24712	270 WIN	22-Oct-89	N	S	28-Sep-15	28-Sep-15	Fired while obstructed	Fired While Obstructed	504108	F	Per Ilion- Check over completely and repair as needed
12478	HANDI-RIFLE	72602	444 MARLIN	10-Feb-11	N	S	28-Sep-15	28-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504106	F	Per Ilion- Check over completely and repair as needed
12482	700	not avail.	3006 SPRG	27-Sep-72	N	PD/S	28-Sep-15	15-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504109	F	Per Ilion- Replace TA and test
12483	700	not avail.	264 WIN MA	15-May-70	N	S	28-Sep-15	15-Oct-15	Delayed Firing - Firearms	Could Not Duplicate Concern	504110	F	Per Ilion- Replace TA and test
12479	700	not avail.	3006 SPRG	21-Jun-84	N	S	28-Sep-15	15-Oct-15	Fired on Bolt Closing	Could Not Duplicate Concern	504058	F	Per Ilion- Replace TA and test
12503	700	25852	222 REM	3-Mar-93	N	S	30-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504188	F	Per Ilion- Replace TA and test
12498	700	not avail.	270 WIN	1-Jan-80	N	S	30-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504199	F	Per Ilion- Replace TA and test
12500	700	27476	270 WIN	27-Jan-00	N	S	30-Sep-15	30-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	504193	F	Per Ilion- Replace TA and test

RAC001244

Confidential

12502	700	not avail.	3006 SPRG	9-Oct-78	N	S	30-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504200	F	Per Ilion- Replace TA and test
12492	700	85435	308 WIN	14-Oct-09	N	S	30-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504201	F	Per Ilion- Replace TA and test
12493	700	not avail.	6MM REM	1-Jan-68	N	S	30-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504181	F	Per Ilion- Replace TA and test
12494	700	not avail.	6MM REM	1-Jan-68	N	S	30-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504180	F	Per Ilion- Replace TA and test
12496	783	85836	3006 SPRG	22-Nov-13	N	S	30-Sep-15	30-Sep-15	Fired on Bolt Closing	Could Not Duplicate Concern	504149	F	Per Ilion- Check over completely and repair as needed
12504	1187	29825	20 GA	7-Oct-13	N	S	30-Sep-15	30-Sep-15	Fired on Bolt Closing	Could Not Duplicate Concern	504209	F	Per Ilion- Check over completely and repair as needed
12495	700	26189	22-250 REM	4-Jun-04	N	PI/S	30-Sep-15	21-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504198	F	Per Ilion- Replace TA and test, Quote for bolt & stock @ discount
12510	700	not avail.	243 WIN	28-Jun-72	N	PI/S	2-Oct-15	30-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504326	F	Per Ilion- Replace TA and test
12516	700	26337	223 REM	13-Dec-07	N	S	2-Oct-15	2-Oct-15	Fired on Bolt Closing	Could Not Duplicate Concern	504304	F	Per Ilion- Replace TA and test
12514	700	27474	243 WIN	2-May-02	N	S	2-Oct-15	2-Oct-15	Other - Firearms	Could Not Duplicate Concern	504327	F	Per Ilion- Replace TA and test
12522	700	not avail.	243 WIN	23-Jan-73	N	S	2-Oct-15	2-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	504325	F	Per Ilion- Replace TA and test
12518	700	not avail.	270 WIN	25-Oct-77	N	S	2-Oct-15	2-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	504300	F	Per Ilion- Replace TA and test
12511	700	25931	3006 SPRG	28-Oct-94	N	S	2-Oct-15	2-Oct-15	Fired on Safe Release	Could Not Duplicate Concern	504329	F	Per Ilion- Replace TA and test
12521	700	not avail.	3006 SPRG	28-Feb-79	N	S	2-Oct-15	2-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504302	F	Per Ilion- Replace TA and test
12519	700	not avail.	308 WIN	1-Sep-74	N	S	2-Oct-15	2-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	504301	F	Per Ilion- Replace TA and test
12517	700	26273	375 RUM	11-Jul-01	N	S	2-Oct-15	2-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504324	F	Per Ilion- Replace TA and test
12512	870	not avail.	12 ga	1-Jul-13	N	S	2-Oct-15	2-Oct-15	Fired Out of Battery	Fired from Contact with Foreign Object	504282	F	Per Ilion- Check over completely
12515	887	82500	12 GA	22-Jun-12	N	S	2-Oct-15	2-Oct-15	Fired With Safe ON	Could Not Duplicate Concern	504322	F	Per Ilion- Check over completely and repair as needed

RAC001245

Confidential

12513	1187	83617	12 GA	5-Jun-12	N	S	2-Oct-15	2-Oct-15	Other - Firearms	Sent in for Evaluation	504285	F	Per Ilion- Check over completely
12531	770	85634	308 WIN	14-Mar-11	Y	PI/S	5-Oct-15	*	Fired on Bolt Closing	Other - Unexamined		F	
12530	597	26550	22 LR	8-Jan-13	N	S	7-Oct-15	7-Oct-15	Defective Parts	Could Not Duplicate Concern	504457	F	Per Ilion- Repair as needed
12539	597	26537	22 LR	6-Aug-13	N	S	7-Oct-15	7-Oct-15	Fired Out of Battery	Other - Unspecified or Undetermined - Ammunition	504482	F	Per Ilion- Check over completely
12533	700	not avail.	270 WIN	27-Jun-80	N	S	7-Oct-15	7-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504444	F	Per Ilion- Replace TA and test
12538	700	84526	MA	15-Jul-15	N	S	7-Oct-15	7-Oct-15	Fired on Bolt Closing	Could Not Duplicate Concern	504493	F	Per Ilion- Replace TA and bolt
12537	700	not avail.	3006 SPRG	4-Dec-80	N	S	7-Oct-15	7-Oct-15	Fired on Bolt Closing	Could Not Duplicate Concern	504492	F	Per Ilion- Replace TA and test
12532	700	not avail.	7MM REM MA	1-Aug-67	N	S	7-Oct-15	7-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504443	F	Per Ilion- Replace TA and test
12536	700	25933	7MM REM MA	15-Aug-00	N	S	7-Oct-15	7-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504510	F	Per Ilion- Replace TA and test
12535	770	85656	3006 SPRG	24-Feb-09	Y	S	7-Oct-15	7-Oct-15	Fired on Bolt Closing	Could Not Duplicate Concern	504524	F	Per Ilion- Replace TA and test
12529	CARBON 15	91037	223/5.56	12-May-14	N	PD/S	7-Oct-15	7-Oct-15	My Gun Blew Up	Wrong Ammunition Fired in Gun	504445	F	Consumer Service replaced with Ramac 90289 in exchange
12552	770	85637	243 WIN	4-Oct-13	Y	PI/S	8-Oct-15	19-Nov-15	Bullet Fragmented	Could Not Duplicate Concern	505699	F	Replace with Ramac 85842 in exchange
12550	597	26516	17 HMR	14-Mar-05	N	PD/S	9-Oct-15	9-Oct-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	504583	F	Per Ilion- Replace with XT17 at n/c
12546	710	27410	3006 SPRG	1-Aug-03	Y	PD/S	9-Oct-15	9-Oct-15	Ammunition Exploded	Over pressured shell	504533	F	Consumer Service replaced with Ramac 85846 in exchange
12548	700	27093	243 WIN	23-Jun-08	N	S	9-Oct-15	9-Oct-15	Fired With Safe ON	Could Not Duplicate Concern	504610	F	Per Ilion- Replace TA and test
12551	700	not avail.	243 WIN	9-Dec-77	N	S	9-Oct-15	9-Oct-15	Fired on Safe Release	Could Not Duplicate Concern	504612	F	Per Ilion- Replace TA and test
12545	700	25709	308 WIN	4-Apr-14	N	S	9-Oct-15	9-Oct-15	Fired on Bolt Closing	Could Not Duplicate Concern	504643	F	Per Ilion- Replace TA and test
12544	770	85653	3006 SPRG	26-Jun-08	Y	S	9-Oct-15	9-Oct-15	Unexplained Discharge Safe OFF	Sent in for Evaluation	504645	F	Per Ilion- Replace TA and bolt and test
12549	CARBON 15	90689	223/5.56	2-Apr-13	N	PD/S	9-Oct-15	9-Oct-15	My Gun Blew Up	Over pressured shell	504559	F	Replace with Ramac 90289 in exchange
12556	700	27474	243 WIN	9-Oct-98	N	S	13-Oct-15	13-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	504701	F	Per Ilion- Replace TA and test
12554	700	not avail.	300 WIN MA	9-Oct-78	N	S	13-Oct-15	13-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	504733	F	Per Ilion- Replace TA and test
12557	700	25775	308 WIN	17-Mar-95	N	S	13-Oct-15	13-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	504732	F	Per Ilion- Replace TA and test

RAC001246

Confidential

12555	700	not avail.	6MM REM	1-Mar-67	N	S	13-Oct-15	13-Oct-15	Fired on Safe Release	Altered Adjustments or Components	504691	F	Per Ilion- Replace TA and test
12558	770	85637	243 WIN	20-Feb-08	Y	S	13-Oct-15	13-Oct-15	Ammunition Exploded	Over pressured shell	504690	F	Per Ilion- Check over completely
12563	700	27389	300 RUM	11-Jun-15	N	PD/S	16-Oct-15	16-Oct-15	Broken Part	Sent in for Evaluation	504919	F	Per Ilion-Replace action and test
12562	700	not avail.	270 WIN	20-Jul-78	N	S	16-Oct-15	16-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	504855	F	Per Ilion- Replace TA and test
12565	700	not avail.	270 WIN	19-Jul-76	N	S	16-Oct-15	16-Oct-15	Unexplained Discharge Safe OFF	Altered Adjustments or Components	504832	F	Per Ilion- Replace TA and test
12561	700	not avail.	6MM REM	16-Feb-72	N	S	16-Oct-15	16-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504854	F	Per Ilion- Replace TA and test
12572	700	not avail.	243 WIN	24-Feb-78	N	S	20-Oct-15	20-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505035	F	Per Ilion- Replace TA and test
12577	700	not avail.	270 WIN	1-May-76	N	S	20-Oct-15	20-Oct-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	505032	F	Per Ilion- Replace TA and test
12574	700	not avail.	3006 SPRG	1-Jun-78	N	S	20-Oct-15	20-Oct-15	Fired on Safe Release	Could Not Duplicate Concern	505037	F	Per Ilion- Replace TA and test
12575	700	not avail.	3006 SPRG	12-Oct-72	N	S	20-Oct-15	20-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	505034	F	Per Ilion- Replace TA and test
12578	700	27095	3006 SPRG	19-Oct-12	N	S	20-Oct-15	20-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504940	F	Per Ilion- Replace TA and test
12573	700	not avail.	7MM REM MA	1-Sep-63	N	S	20-Oct-15	20-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	505036	F	Per Ilion- Replace TA and test
12580	700	not avail.	7MM REM MA	1-Mar-68	N	S	20-Oct-15	20-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	505031	F	Per Ilion- Replace TA and test
12579	770	85632	270 WIN	27-Mar-07	Y	S	20-Oct-15	20-Oct-15	Fired on Bolt Opening	Sent in for Evaluation	504941	F	Per Ilion- Check over completely
12576	SEVEN	not avail.	7MM-08 REM	1-Mar-94	N	S	20-Oct-15	20-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505033	F	Per Ilion- Replace TA and test
12588	700	84344	220 SWIFT	17-Jul-13	N	PD/S	22-Oct-15	22-Oct-15	Ammunition Exploded	Sent in for Evaluation	505117	F	Per Ilion- Check over completely and repair as needed
12589	700	84203	308 WIN	31-May-13	N	S	23-Oct-15	4-May-16	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Rifle not returned to Ilion for exam
12593	700	84207	308 WIN	12-Jun-09	N	PI/PD/S	26-Oct-15	26-Oct-15	Case Failure	Sent in for Evaluation	505094	F	Check over completely, repair as needed, and test at no charge
12597	700	not avail.	243 WIN	22-Oct-76	N	S	26-Oct-15	28-Oct-15	Fired on Safe Release	Sent in for Evaluation	505142	F	Per Ilion- Replace TA and test

RAC001247

Confidential

12600	700	not avail.	3006 SPRG 7MM REM	13-Oct-69 1-Aug-74	N	S	26-Oct-15	26-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505245	F	Per Ilion- Replace TA and test
12598	700	not avail.	MA	1-Aug-74	N	S	26-Oct-15	28-Oct-15	Fired With Safe ON	Sent in for Evaluation	505140	F	Per Ilion- Replace TA and test
12599	700	not avail.	7MM REM MA	15-Jul-83	N	S	26-Oct-15	26-Oct-15	Unexplained Discharge Safe ON	Could Not Duplicate Concern	505228	F	Per Ilion- Replace TA and test
12601	700	not avail.	7MM REM MA	22-Mar-72	N	S	26-Oct-15	28-Oct-15	Fired on Bolt Closing	Altered Adjustments or Components	505246	F	Per Ilion- Replace TA and test
12596	870	81214	12 GA 7MM-08	4-Sep-13	N	S	26-Oct-15	26-Oct-15	Fired on Bolt Closing	Could Not Duplicate Concern	505114	F	Per Ilion- Check over completely
12594	SEVEN	24786	REM	14-Apr-90	N	S	26-Oct-15	28-Oct-15	Fired on Bolt Closing	Could Not Duplicate Concern	505141	F	Per Ilion- Replace TA and test
12602	1187	27081	12 GA	24-May-07	N	PD/S	26-Oct-15	5-Nov-15	My Gun Blew Up	Fired from Contact with Foreign Object	505239	F	Replace with Ramac 81049 in exchange
12595	CARBON 15	91036	223/5.56	14-Apr-14	Y	PD/S	26-Oct-15	5-Jan-16	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	505143	F	Per Ilion- Replace at no charge
									Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern			
12604	700	25767	243 WIN	15-Aug-90	N	PI/S	27-Oct-15	18-Nov-15	Fired on Safe Release	Could Not Duplicate Concern	505303	F	Per Ilion- Replace TA and test
12607	700	25773	3006 SPRG	27-Nov-01	N	S	29-Oct-15	29-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505465	F	Per Ilion- Replace TA and test
12608	700	25634	3006 SPRG 7MM REM	14-Oct-93	N	S	29-Oct-15	29-Oct-15	Fired on Safe Release	Could Not Duplicate Concern	505302	F	Per Ilion- Replace TA and test
12606	700	not avail.	MA	12-Aug-69	N	S	29-Oct-15	29-Oct-15	Fired on Safe Release	Improper Maintenance	505297	F	Per Ilion- Replace TA and test
12609	VERSA MAX	81048	12 GA	2-Mar-12	N	PI/S	29-Oct-15	9-Nov-15	Broken Part	Could Not Duplicate Concern	505458	F	Repair @ n/c - goodwill gesture
12605	597	80850	22 LR	9-Jul-07	N	S	29-Oct-15	5-Nov-15	Went Automatic	Could Not Duplicate Concern	505296	F	Check over completely, repair as needed, and test at no charge
12610	SEVEN	29551	7MM SAUM	31-Jan-03	N	S	29-Oct-15	9-Nov-15	Other - Firearms - XMP Update	Could Not Duplicate Concern	505463	F	Per Ilion- Replace TA and test
12611	DPMS A-15	60531	5.56	10-Apr-15	N	PD/S	29-Oct-15	29-Oct-15	Unknown Claim	Over pressured shell	505464	F	Replace with Ramac 60531 in exchange at a 50% discount
12617	700	27255	300 WSM	7-Feb-09	N	S	2-Nov-15	7-Dec-15	Fired on Safe Release	Other - Unexamined	See Case 12729	F	See Case 12729
12625	770	85633	3006 SPRG	19-Mar-07	Y	PI/PD/S	3-Nov-15	13-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505528	F	Per Ilion- Replace TA and test
12628	700	85435	308 WIN	8-Dec-10	N	PI/S	3-Nov-15	3-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505595	F	Per Ilion- Replace TA and test
12621	700	not avail.	25-06 REM	22-Feb-71	N	S	3-Nov-15	3-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505596	F	Per Ilion- Replace TA and test
12629	700	not avail.	270 WIN	27-Apr-73	N	S	3-Nov-15	3-Nov-15	Fired on Bolt Closing	Altered Adjustments or Components	505598	F	Per Ilion- Replace TA and test
12631	700	27476	270 WIN	17-Jun-03	N	S	3-Nov-15	3-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505594	F	Per Ilion- Replace TA and test

RAC001248

Confidential

12632	700	25773	3006 SPRG	11-Apr-89	N	S	3-Nov-15	3-Nov-15	Fired on Bolt Closing	Could Not Duplicate Concern	505597	F	Per Ilion- Replace TA and test
12626	700	not avail.	308 WIN	1-Aug-62	N	S	3-Nov-15	3-Nov-15	Fired on Safe Release	Altered Adjustments or Components	505529	F	Per Ilion- Replace TA and test
12624	700	not avail.	7MM REM MA	1-Apr-83	N	S	3-Nov-15	3-Nov-15	Fired on Safe Release	Altered Adjustments or Components	505531	F	Per Ilion- Replace TA and test
12630	700 ML	27572	50 CAL	7-Nov-96	N	S	3-Nov-15	3-Nov-15	Fired on Safe Release	Could Not Duplicate Concern	505569	F	Per Ilion- Replace TA and test
12620	Excel Auto	72350	12 GA	7-Sep-13	Y	S	3-Nov-15	4-Dec-15	Fired With Safe ON	Sent in for Evaluation	505532	F	CSR in the Call Center replaced shotgun through SNC
12637	783	85837	308 WIN	19-Sep-13	N	PD/S	5-Nov-15	5-Nov-15	Barrel Burst/Split (Other than Chamber)	Fired While Obstructed	505657	F	Per Ilion, replace in exchange with Ramac 85847 at no charge.
12634	700	27011	270 WIN	1-Sep-06	N	S	5-Nov-15	5-Nov-15	Fired on Safe Release	Could Not Duplicate Concern	505604	F	Per Ilion- Replace TA and test
12635	700	29663	308 WIN	21-Oct-09	N	S	5-Nov-15	5-Nov-15	Fired on Safe Release	Could Not Duplicate Concern	505659	F	Per Ilion- Replace TA and test
12638	700	not avail.	7MM REM MA	6-Jun-73	N	S	5-Nov-15	5-Nov-15	Fired on Bolt Closing	Could Not Duplicate Concern	505621	F	Per Ilion- Replace TA and test
12636	870	25561	20 GA	9-Dec-14	N	S	5-Nov-15	5-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505660	F	Per Ilion- Check over completely and repair as needed
12640	Handi-Rifle	72530	280 REM	15-Jul-09	N	S	5-Nov-15	5-Nov-15	Case Separation	Sent in for Evaluation	505669	F	Per Ilion- Check over completely and repair as needed
12648	700	not avail.	243 WIN	26-Jun-75	N	S	9-Nov-15	9-Nov-15	Unexplained Discharge - No Mention of Safety Position	AFT MKT TRIGGER ASSM	505780	F	Per Ilion- Replace TA and test
12642	700	not avail.	270 WIN	20-Sep-71	N	S	9-Nov-15	9-Nov-15	Fired on Bolt Closing	Improper Maintenance	505776	F	Per Ilion- Replace TA and test
12644	700	not avail.	270 WIN	19-Jul-78	N	S	9-Nov-15	9-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505772	F	Per Ilion- Replace TA and test
12643	700	27535	300 WIN MA	5-Jan-99	N	S	9-Nov-15	9-Nov-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	505778	F	Per Ilion- Replace TA and test
12641	770	85649	243 WIN	1-Jul-13	Y	S	9-Nov-15	9-Nov-15	Fired on Bolt Closing	Could Not Duplicate Concern	505774	F	Per Ilion- Check over completely and repair as needed
12645	7400	29769	3006 SPRG	22-Mar-96	N	S	9-Nov-15	9-Nov-15	Went Automatic	Could Not Duplicate Concern	505777	F	Per Ilion- Replace TA and test
12649	700	N/A	270 WIN	12-Jan-72	N	PI/PD/S	9-Nov-15	16-Dec-15	Fired With Safe ON	Could Not Duplicate Concern	507074	F	Check over completely, repair as needed, and test at no charge
12646	CARBON 15	90689	5.56	17-Jul-12	N	PD/S	9-Nov-15	9-Nov-15	My Gun Blew Up	Case Separation	505741	F	Replace with Ramac 90289 in exchange
12647	552	25594	22 RF	5-Aug-14	N	S	9-Nov-15	27-Jan-16	Fired Out of Battery	Could Not Duplicate Concern	507941	F	Per Release - Check for \$607.45 (refund of firearm & shipping)
12651	700	84342	22-250 REM	2-Apr-15	N	PD/S	10-Nov-15	10-Nov-15	Broken Part	Other - Unspecified or Undetermined - Ammunition	505844	F	Per Ilion- Check over completely
12654	770	85634	308 WIN	8-Nov-12	Y	PD/S	10-Nov-15	10-Nov-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	505863	F	Per Ilion- Check over completely

RAC001249

Confidential

12655	700	25787	243 WIN	13-Feb-86	N	S	10-Nov-15	10-Nov-15	Ammunition Exploded	Other - Unspecified or Undetermined - Ammunition	505848	F	Per Ilion- Check over completely
12652	700	25791	270 WIN	21-Oct-88	N	S	10-Nov-15	10-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505866	F	Per Ilion- Replace TA and test
12653	700	not avail.	3006 SPRG	3-Apr-69	N	S	10-Nov-15	10-Nov-15	Fired With Safe ON	Could Not Duplicate Concern	505795	F	Per Ilion- Replace TA and test
12657	VERSA MAX	83500	12 GA	23-Sep-15	N	S	10-Nov-15	10-Nov-15	Fired on Safe Release	Could Not Duplicate Concern	505843	F	Per Ilion- Check over completely
12660	710	27412	7MM MAG	10-Feb-06	Y	S/C	12-Nov-15	18-Dec-15	Jamming/Feeding issues	Sent in for Evaluation	507061	F	Replace w/85848 in exchange through SNC order
12667	597	26516	17 HMR	13-Jun-03	N	PD/S	13-Nov-15	19-Nov-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	505875	F	Converting to 22 WMR as requested by customer
12664	700	84600	223 REM	8-Jan-13	N	S	13-Nov-15	13-Nov-15	Ammunition Exploded	Other - Unspecified or Undetermined - Ammunition	505950	F	Per Ilion- Check over completely and repair as needed
12665	700	85508	300 WIN MA		N	S	13-Nov-15	13-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505980	F	Per Ilion- Replace TA and test
12662	700	84207	308 WIN	16-Jan-09	N	S	13-Nov-15	19-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505981	F	Repair @ n/c under XMP recall
12666	700	29663	308 WIN	11-Oct-07	N	S	13-Nov-15	13-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505979	F	Per Ilion- Replace TA and test
12663	XM15-E2S	90391	223/5.56	4-Oct-13	N	PD/S	13-Nov-15	13-Nov-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	505935	F	Check over completely, repair as needed, and test at a 50% discount
12678	1100	not avail.	12 GA	1-Aug-85	N	PD/S	17-Nov-15	17-Nov-15	Ammunition Exploded	Other - Unspecified or Undetermined - Ammunition	506097	F	Per Ilion- Check over completely
12679	700	not avail.	270 WIN	17-Dec-69	N	S	17-Nov-15	17-Nov-15	Fired on Bolt Closing	Could Not Duplicate Concern	506054	F	Per Ilion- Replace TA and test
12684	700	not avail.	270 WIN	19-Jan-72	N	S	17-Nov-15	23-Nov-15	Other - Firearms - XMP Update	Could Not Duplicate Concern	506094	F	Per Ilion- Replace TA and test
12680	700	25807	300 WIN MA	1-Mar-05	N	S	17-Nov-15	17-Nov-15	Fired on Safe Release	Could Not Duplicate Concern	506098	F	Per Ilion- Replace TA and test
12683	700	not avail.	3006 SPRG	30-May-80	N	S	17-Nov-15	17-Nov-15	Fired on Bolt Closing	Could Not Duplicate Concern	506051	F	Per Ilion- Replace TA and test
12682	700	25803	7MM REM MA	10-Apr-02	N	S	17-Nov-15	20-Nov-15	Fired on Bolt Closing	Could Not Duplicate Concern	506093	F	Per Ilion- Replace TA and test
12685	722	not avail.	222 REM	1-Jun-57	Y	S	17-Nov-15	30-Nov-15	Fired on Safe Release	Altered Adjustments or Components	506049	F	Per Ilion- Replace TA and test
12681	700	not avail.	3006 SPRG	11-Feb-77	N	PD/S	17-Nov-15	4-Dec-15	Fired on Bolt Closing	Could Not Duplicate Concern	506118	F	Replace TA @ n/c - goodwill
12700	700	84275	3006 SPRG	17-Oct-14	N	PD/S	20-Nov-15	20-Nov-15	Barrel Burst/Split (Other than Chamber)	Fired While Obstructed	506285	F	Per Ilion - Quote to repair @ discount
12701	870	25568	12 GA	12-Feb-14	N	PD/S	20-Nov-15	20-Nov-15	Barrel Burst/Split (Other than Chamber)	Fired While Obstructed	506283	F	Per Ilion, replace in exchange with Ramac 25568 at 50% discount.

RAC001250

Confidential

12692	1187	26920	20 GA	31-Jan-06	N	PD/S	20-Nov-15	20-Nov-15	My Gun Blew Up	Slow to Peak	506257	F	Per Ilion, check over completely, repair as needed, and test at no charge.
12690	7400	29767	308 WIN	15-Jan-93	Y	PD/S	20-Nov-15	20-Nov-15	Barrel Burst/Split (Other than Chamber)	Fired While Obstructed	506191	F	Per Ilion, check over completely, repair as needed, and test at a 50% discount.
12694	700	not avail.	270 WIN	7-Oct-76	N	PI/S	20-Nov-15	20-Nov-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	506241	F	Per Ilion, check over completely, repair as needed, and test at no charge.
12693	673	24687	350 REM MA	3-Jul-03	N	S	20-Nov-15	20-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506174	F	Per Ilion, check over completely, repair as needed, and test at no charge.
12697	700	85206	270 WIN	7-Jan-14	N	S	20-Nov-15	20-Nov-15	Fired With Safe ON	Could Not Duplicate Concern	506168	F	Per Ilion replace trigger at no charge.
12698	700	not avail.	6MM REM	29-Feb-72	N	S	20-Nov-15	20-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506173	F	Per Ilion - Replace TA & test @ n/c
12691	770	85649	243 WIN	21-Nov-12	Y	S	20-Nov-15	20-Nov-15	Fired on Safe Release	Could Not Duplicate Concern	506219	F	Per Ilion, check over completely, repair as needed, and test at no charge.
12696	SPORTSMAN 78	not avail.	308 WIN	17-Sep-88	N	S	20-Nov-15	20-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506242	F	Per Ilion, check over completely, repair as needed, and test at no charge.
12699	H&R HANDI RIFLE	72654	243 WIN	21-Apr-06	Y	PI/S	20-Nov-15	28-Jan-16	Ammunition Exploded	Other - Unspecified or Undetermined - Ammunition	506284	F	Per Release - Replace w/27355 in exchange
12704	700	N/A	3006 SPRG	19-Feb-82	N	S	25-Nov-15	22-Dec-15	Fired on Bolt Closing	Could Not Duplicate Concern	507531	F	Per Ilion, check over completely, repair as needed, and test at no charge.
12705	700	25798	223 REM	25-Jan-86	N	S	30-Nov-15	9-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506441	F	Per Ilion - Replace TA & test @ n/c
12709	700	not avail.	3006 SPRG	6-Jul-71	N	S	30-Nov-15	9-Dec-15	Fired on Bolt Closing	Altered Adjustments or Components	506408	F	Per Ilion - Replace TA & test @ n/c
12710	700	25759	6.5 X 55 S	5-Jan-94	N	S	30-Nov-15	8-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506175	F	Per Ilion - Replace TA & test @ n/c
12714	770	85632	270 WIN	4-Jan-11	Y	S	30-Nov-15	4-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506376	F	Per Ilion - Repair at n/c
12712	SEVEN	24741	7MM-08 REM	4-May-98	N	S	30-Nov-15	16-Dec-15	Fired on Safe Release	Altered Adjustments or Components	506405	F	Per Ilion - Replace TA & test @ n/c - goodwill
12713	700	N/A	243 WIN	8-Mar-83	N	S	30-Nov-15	30-Nov-15	Delayed Firing - Firearms	Could Not Duplicate Concern	506307	F	Per Ilion, check over completely, repair as needed, and test at no charge
12726	700	25767	243 WIN	3-Apr-85	N	S	2-Dec-15	2-Dec-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	506561	F	Per Ilion, replace trigger assembly, check over at no charge

RAC001251

Confidential

12716	700	27095	3006 SPRG	9-Oct-12	N	S	2-Dec-15	2-Dec-15	Fired on Bolt Closing	Could Not Duplicate Concern	506467	F	Per Iliion, replace trigger assembly, check over at no charge
12722	700	27196	3006 SPRG	14-Jun-10	N	S	2-Dec-15	9-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	506609	F	Per Iliion - Repair at n/c, XMP update
12717	887	82502	12 GA	28-Mar-14	N	S	2-Dec-15	7-Jan-16	Fired on Bolt Closing	Could Not Duplicate Concern	506460	F	Refund check \$520
12734	700	25771	270 WIN	28-Sep-95	N	S	3-Dec-15	3-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506621	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge
12733	700	25735	300 RUM	24-Jul-00	N	S	3-Dec-15	3-Dec-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	506619	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge
12729	700	27255	300 WSM	7-Feb-09	N	S	3-Dec-15	3-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	506565	F	Per Iliion - Replace TA & test @ n/c
12738	700	27478	3006 SPRG	19-Aug-98	N	S	3-Dec-15	10-Dec-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	506748	F	Per Iliion - Replace TA & test @ n/c
12731	700	26917	308 WIN	16-Nov-95	N	S	3-Dec-15	3-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506620	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge
12736	700	not avail.	308 WIN	5-Jul-72	N	S	3-Dec-15	10-Dec-15	Fired on Bolt Closing	Could Not Duplicate Concern	506583	F	Per Iliion - Replace TA & test @ n/c
12730	770	85648	300 WIN MA	27-May-09	Y	S	3-Dec-15	10-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506558	F	Per Iliion - Replace TA & test @ n/c - goodwill
12732	78 Sportsman	26164	3006 SPRG	22-Jul-87	Y	S	3-Dec-15	3-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506584	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge
12780	Savage AXIS	n/a	7MM MAG		N	PI/PD/S	4-Dec-15	5-Apr-16	Ammunition Mixed In Box	Other - Unspecified or Undetermined - Ammunition	n/a	A	Per Release - Replace w/84163 in exchange
12752	700	27490	223 REM	7-Feb-95	N	S	8-Dec-15	8-Dec-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	506747	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge
12748	700	not avail.	270 WIN	21-May-75	N	S	8-Dec-15	11-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	506746	F	Per Iliion - Replace TA & test @ n/c
12749	700	25632	280 REM	13-Mar-86	N	S	8-Dec-15	8-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	506679	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge
12750	700 ML	27572	50 CAL	28-Aug-96	N	S	8-Dec-15	8-Dec-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	506749	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge
12756	660	N/A	243 WIN	1-Jul-67	Y	S	9-Dec-15	9-Dec-15	Other - Firearms	Altered Adjustments or Components	506930	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge
12759	700	25614	243 WIN	16-Aug-89	N	S	9-Dec-15	9-Dec-15	Fired With Safe ON	Altered Adjustments or Components	506928	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge
12760	700	N/A	270 WIN	12-Sep-73	N	S	9-Dec-15	9-Dec-15	Unexplained Discharge - No Mention of Safety Position	AFT MKT TRIGGER ASSM	506926	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge

RAC001252

Confidential

12761	700	N/A	3006 SPRG	30-Jan-73	N	S	9-Dec-15	9-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	506922	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12758	Excel Auto	72350	12 GA	20-May-14	Y	S	9-Dec-15	9-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	506924	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12757	SEVEN	29555	300 SAUM	7-May-03	N	S	9-Dec-15	9-Dec-15	Fired on Safe Release	Altered Adjustments or Components	506929	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12766	700	25773	270 WIN	13-Jan-94	N	S	10-Dec-15	10-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506925	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12767	700	N/A	7MM REM MA	21-Sep-77	N	S	10-Dec-15	10-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506932	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12776	Axis	N/a	30/06		N	PD/S	11-Dec-15	22-Dec-15	Wrong Ammunition Fired in Gun	Wrong Ammunition Fired in Gun	n/a	A	Locate to cover costs (\$350) Check over completely, repair as needed, and test at no charge
12800	887	82540	12 GA	25-Apr-14	N	PD/S	14-Dec-15	30-Dec-15	Fired With Safe ON	Could Not Duplicate Concern	507109	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12786	700	not avail.	3006 SPRG	1-Jul-71	N	PI/S	14-Dec-15	16-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507060	F	Per Ilion - Replace TA & test @ n/c
12799	700	not avail.	270 WIN	2-Feb-79	N	S	14-Dec-15	18-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507131	F	Per Ilion - Replace TA & test @ n/c
12802	700	N/A	300 WIN MA	21-Oct-79	N	S	14-Dec-15	14-Dec-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	507129	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12801	700	27255	300 WSM	16-Nov-06	N	S	14-Dec-15	18-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	507248	F	Per Ilion - Replace TA & test @ n/c
12789	700	26035	3006 SPRG	21-Jan-98	N	S	14-Dec-15	14-Dec-15	Fired on Bolt Closing	Could Not Duplicate Concern	507068	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12791	700	not avail.	3006 SPRG	21-Mar-83	N	S	14-Dec-15	17-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507062	F	Per Ilion - Replace TA & test @ n/c
12794	700	25773	3006 SPRG	14-Aug-97	N	S	14-Dec-15	14-Dec-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	507132	F	Per Ilion, replace trigger assembly at no charge, replace bolt at 25% discount
12796	700	not avail.	3006 SPRG	13-Nov-69	N	S	14-Dec-15	18-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	507130	F	Per Ilion - Replace TA & test @ n/c
12797	700	84467	308 WIN	31-Jul-09	N	S	14-Dec-15	17-Dec-15	Other- Firearms - XMP Update	Could Not Duplicate Concern	507111	F	Per Ilion - Replace TA @ n/c
12793	700	N/A	7MM REM MA	2-Jun-72	N	S	14-Dec-15	14-Dec-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	507059	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12785	788	N/A	30-30 WIN	1-Jan-67	Y	S	14-Dec-15	14-Dec-15	Fired on Bolt Closing	Could Not Duplicate Concern	507073	F	Per Ilion, check over completely, repair as needed, and test at no charge as a goodwill gesture

RAC001253

Confidential

12787	R-25	60030	243 WIN	17-Oct-14	N	S	14-Dec-15	17-Dec-15	Fired on Safe Release	Altered Adjustments or Components	507065	F	Per Iliion - Quote to repair
12804	1187	83680	12 GA	29-Oct-07	N	PD/S	14-Dec-15	15-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	508265	F	Check over completely, repair as needed, and test at no charge
12813	700	26109	17 REM	20-Jan-00	N	S	16-Dec-15	13-Jan-16	Fired on Bolt Closing	Could Not Duplicate Concern	507367	F	Per Iliion - Replace TA & test @ n/c
12819	700	27478	3006 SPRG	31-Aug-95	N	S	16-Dec-15	12-Jan-16	Fired on Bolt Closing	Could Not Duplicate Concern	507394	F	Per Iliion - Replace TA & test @ n/c
12816	700	27480	7MM REM MA	17-Nov-99	N	S	16-Dec-15	25-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507395	F	Per Iliion - Replace TA & test @ n/c
12817	700	not avail.	7MM REM MA	1-Apr-67	N	S	16-Dec-15	12-Jan-16	Delayed Firing - Firearms	Could Not Duplicate Concern	507393	F	Per Iliion - Replace TA & test @ n/c
12815	710	27410	3006 SPRG	28-Jul-03	Y	S	16-Dec-15	13-Jan-16	Delayed Firing - Firearms	Could Not Duplicate Concern	507352	F	Replace w/85846 in exchange
12821	700	not avail.	270 WIN	13-Apr-82	N	S	17-Dec-15	11-Jan-16	Fired on Bolt Closing	Could Not Duplicate Concern	507368	F	Per Iliion - Replace TA & test @ n/c
12844	700 ML	27580	50 CAL	23-Jul-97	N	PD/S	22-Dec-15	22-Dec-15	Fired on Safe Release	Altered Adjustments or Components	507790	F	Per Iliion - Replace TA & test @ n/c
12839	700	not avail.	270 WIN	1-Aug-66	N	S	22-Dec-15	28-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	507799	F	Per Iliion - Replace TA & test @ n/c
12824	700	not avail.	3006 SPRG	1-Jun-67	N	S	22-Dec-15	22-Dec-15	Fired on Bolt Opening	Could Not Duplicate Concern	507500	F	Per Iliion - Replace TA & test @ n/c
12830	700	not avail.	308 WIN	16-Jul-71	N	S	22-Dec-15	28-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	507536	F	Per Iliion - Replace TA & test @ n/c
12829	700	not avail.	6MM REM	10-Nov-76	N	S	22-Dec-15	28-Dec-15	Fired on Safe Release	Altered Adjustments or Components	507547	F	Per Iliion - Replace TA & test @ n/c
12826	721	not avail.	3006SPRG	1-Jan-64	Y	S	22-Dec-15	22-Dec-15	Fired on Bolt Closing	Sent in for Evaluation	507540	F	Per Iliion - Replace TA & test @ n/c
12843	770	85654	7MM REM MA	31-Mar-09	Y	S	22-Dec-15	22-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	507800	F	Per Iliion, replace trigger assembly, check over, and test fire at no charge
12831	700	25773	3006 SPRG	31-Aug-95	N	S	22-Dec-15	25-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507537	F	Per Iliion - Replace TA & test @ n/c
12836	700	not avail.	3006 SPRG	26-Oct-71	N	S	22-Dec-15	14-Jan-16	Fired on Safe Release	Altered Adjustments or Components	507541	F	Per Iliion - Replace TA & test @ n/c
12832	700	85435	308 WIN	31-Jan-11	N	S	22-Dec-15	25-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507539	F	Per Iliion - Replace TA & test @ n/c
12828	700	not avail.	6MM REM	17-Aug-70	N	S	22-Dec-15	27-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507535	F	Per Iliion - Replace TA & test @ n/c
12835	700	not avail.	7MM REM MA	9-Jan-73	N	S	22-Dec-15	14-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507532	F	Per Iliion - Replace TA & test @ n/c
12842	710	27408	270 WIN	10-Nov-05	N	S	22-Dec-15	11-Jan-16	Fired on Safe Release	Altered Adjustments or Components	507796	F	Replace w/ramac 85844 in exchange
12827	710	27410	3006 SPRG	7-Feb-05	Y	S	22-Dec-15	28-Jan-16	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	507533	F	Replace w/85846 in exchange
12847	700	not avail.	3006 SPRG	29-Nov-72	N	S	23-Dec-15	23-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	507793	F	Per Iliion - Replace TA & test @ n/c

RAC001254

Confidential

12849	597	26513	22 LR	14-Nov-14	N	S	23-Dec-15	23-Dec-15	Went Automatic	Could Not Duplicate Concern	507682	F	Per Ilion, check over completely, repair as needed, and test at no charge
12851	700	N/A	3006 SPRG	27-Jul-72	N	PD/S	28-Dec-15	5-Feb-16	Fired on Safe Release	Altered Adjustments or Components	509376	F	Check over completely, repair as needed, and test at no charge
12858	700	29708	270 WIN	5-Aug-92	N	S	29-Dec-15	29-Dec-15	Delayed Firing - Firearms	Could Not Duplicate Concern	507939	F	Per Ilion - Replace TA & test @ n/c
12856	700	84218	308 WIN	31-Jan-12	N	S	29-Dec-15	29-Dec-15	Fired on Safe Release	Altered Adjustments or Components	507901	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12857	SEVEN	24743	308 WIN	1-Aug-02	N	S	29-Dec-15	18-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507906	F	Per Ilion - Replace TA & test @ n/c
12859	597	26536	17 HMR	26-Sep-02	N	PD/S	29-Dec-15	29-Dec-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	507940	F	Per Ilion, converting to 22 WMR as requested by customer
12854	788	not avail.	6MM REM	4-Sep-73	Y	S	29-Dec-15	29-Dec-15	Fired on Bolt Closing	Could Not Duplicate Concern	507870	F	Per Ilion - Check over, clean, test @ n/c - goodwill
12864	700	not avail.	3006 SPRG	13-Sep-76	N	S	31-Dec-15	31-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	508013	F	Per Ilion - Replace TA & test @ n/c
12863	700	25815	7MM REM MA	7-Sep-04	N	S	31-Dec-15	31-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	508001	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12868	700	25803	7MM REM MA	7-Oct-86	N	S	31-Dec-15	31-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	508030	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12869	700	N/A	7MM REM MA	29-Oct-71	N	S	31-Dec-15	31-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	508029	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12867	715	85800	243 WIN	16-Nov-06	Y	S	31-Dec-15	5-Feb-16	Fired on Safe Release	Altered Adjustments or Components	508021	F	Per Ilion - Repair at n/c - goodwill
12874	DPMS A-15	60531	223 REM	14-Jul-15	N	PD/S	4-Jan-16	20-Jan-16	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	508817	F	Returned as Received
12885	870	81283	20 GA	17-Jul-14	N	PD/S	5-Jan-16	21-Jan-16	Fired on Bolt Closing	Could Not Duplicate Concern	508815	F	Check over completely, repair as needed, and test at no charge
12883	700	not avail.	270 WIN	11-May-80	N	PD/S	6-Jan-16	22-Jan-16	Fired on Safe Release	Could Not Duplicate Concern	508180	F	Per Ilion - Replace TA & test @ n/c
12880	700	not avail.	3006 SPRG	27-Aug-76	N	PD/S	6-Jan-16	28-Jan-16	Fired on Safe Release	Could Not Duplicate Concern	508182	F	Per Ilion - Replace TA & test @ n/c
12882	770	85646	270 WIN	24-Aug-11	Y	PD/S	6-Jan-16	6-Jan-16	Fired on Bolt Closing	Could Not Duplicate Concern	508098	F	Per Ilion - Replace TA & test @ n/c
12884	700	not avail.	270 WIN	1-Apr-68	N	S	6-Jan-16	25-Jan-16	Fired on Bolt Closing	Improper Maintenance	508181	F	Per Ilion - Replace TA & test @ n/c
12879	700	85336	3006 SPRG	3-Apr-14	N	S	6-Jan-16	6-Jan-16	Fired on Safe Release	Altered Adjustments or Components	508141	F	Per Ilion - Replace TA & test @ n/c
12878	770	85648	300 WIN MA	27-May-09	Y	S	6-Jan-16	6-Jan-16	Fired on Bolt Closing	Could Not Duplicate Concern	508139	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12886	887	82540	12 GA	17-Oct-13	N	S	6-Jan-16	6-Jan-16	Failed to Extract	Could Not Duplicate Concern	508120	F	Replace with Ramac 81198 in exchange
12899	700	not avail.	REM	23-Feb-79	N	S	8-Jan-16	27-Jan-16	Fired on Bolt Closing	Could Not Duplicate Concern	508262	F	Per Ilion - Replace TA & test @ n/c

RAC001255

Confidential

12896	700	not avail.	243 WIN	21-Nov-75	N	S	8-Jan-16	8-Jan-16	Fired on Bolt Closing	Improper Maintenance	508236	F	Per Ilion - Replace TA & test @ n/c	
12897	700	27253	270 WSM	2-May-06	N	S	8-Jan-16	8-Jan-16	Fired on Safe Release	Could Not Duplicate Concern	508272	F	Per Ilion - Replace TA & test @ n/c	
12902	700	27478	3006 SPRG	24-May-02	N	S	8-Jan-16	8-Jan-16	Fired on Safe Release	Improper Maintenance	508312	F	Per Ilion - Replace TA & test @ n/c	
12895	783	85782	243 WIN	28-Aug-15	N	S	8-Jan-16	8-Jan-16	Fired With Safe ON	Broken or Missing Parts	508261	F	Per Ilion - Check over completely and repair as needed at no charge	
12898	710	27410	3006 SPRG	10-May-04	Y	S	8-Jan-16	9-Feb-16	Fired on Bolt Closing	Altered Adjustments or Components	508263	F	Replace w/85846 in exchange	
12929	783	85847	308 WIN	10-Mar-15	N	S	11-Jan-16	29-Jan-16	Fired on Safe Release	Other - Unexamined	n/a	F	Refunded purchase price.	
12928	700	29709	270 WIN	7-Apr-93	N	S	13-Jan-16	13-Jan-16	Fired on Bolt Closing	Improper Maintenance	508509	F	Per Ilion - Replace TA & test @ n/c	
12921	700	not avail.	3006 SPRG	1-Sep-74	N	S	13-Jan-16	13-Jan-16	Fired on Safe Release	Improper Maintenance	508410	F	Per Ilion - Replace TA & test @ n/c	
12922	700	not avail.	6MM REM	12-Jul-73	N	S	13-Jan-16	27-Jan-16	Fired on Bolt Closing	Altered Adjustments or Components	508338	F	Per Ilion - Replace TA & test @ n/c	
12926	783	85847	308 WIN	12-Mar-15	N	S	13-Jan-16	13-Jan-16	Fired on Safe Release	Could Not Duplicate Concern	508343	F	Per Ilion, check over completely, repair as needed, and test at no charge.	
12925	SEVEN	85419	300 BLK OU	28-Aug-12	N	S	13-Jan-16	13-Jan-16	Fired on Safe Release	Could Not Duplicate Concern	508390	F	Per Ilion - Replace TA & test @ n/c	
12914	870	81125	12 GA	14-Jan-15	N	PD/S	13-Jan-16	9-Feb-16	Fired Out of Battery	Slow to Peak	508440	F	Per Ilion, check over completely, repair as needed, and test at no charge.	
12917	870	25583	20 GA	11-Sep-13	N	S	13-Jan-16	9-Feb-16	Fired With Safe ON	Could Not Duplicate Concern	508406	F	Per Ilion - Repair at n/c	
12927	552	25594	22 RF	19-May-15	N	S	13-Jan-16	13-Jan-16	Fired on Safe Release	Could Not Duplicate Concern	508463	F	Per Ilion - Check over, clean, test @ n/c	
12948	700	27092	243 WIN	21-Nov-06	N	PD/S	15-Jan-16	18-Jan-16	Fired on Bolt Closing	Altered Adjustments or Components	508656	F	Replace TA & test @ n/c - goodwill	
12939	700	not avail.	270 WIN	13-Oct-71	N	S	15-Jan-16	29-Jan-16	Fired on Bolt Opening	Could Not Duplicate Concern	508633	F	Per Ilion - Replace TA & test @ n/c	
12945	700	not avail.	300 WIN MA	1-Sep-66	N	S	15-Jan-16	28-Jan-16	Fired on Safe Release	Unexplained Discharge - No Mention of Safety Position	508635	F	Per Ilion - Replace TA & test @ n/c	
12940	700	not avail.	3006 SPRG	25-Feb-77	N	S	15-Jan-16	28-Jan-16	Fired on Safe Release	Unexplained Discharge - No Mention of Safety Position	508598	F	Per Ilion - Replace TA & test @ n/c	
12949	700	not avail.	3006 SPRG	7-Sep-71	N	S	15-Jan-16	28-Jan-16	Fired on Safe Release	Unexplained Discharge - No Mention of Safety Position	508596	F	Per Ilion - Replace TA & test @ n/c	
12946	700	not avail.	6MM REM	13-May-71	N	S	15-Jan-16	15-Jan-16	Fired on Bolt Closing	Unexplained Discharge - No Mention of Safety Position	508597	F	Per Ilion - Replace TA & test @ n/c	
12943	SEVEN	24784	6MM REM	12-May-83	N	S	15-Jan-16	15-Jan-16	Fired on Bolt Closing	Unexplained Discharge - No Mention of Safety Position	508663	F	Per Ilion - Replace TA & test @ n/c	
12947	788	not avail.	243 WIN	7-Jun-77	Y	S	15-Jan-16	9-Feb-16	Fired on Bolt Closing	Unexplained Discharge - No Mention of Safety Position	508586	F	Per Ilion - Check over, clean, test @ n/c	
12952	700	25803	7MM REM MA	18-Oct-87	N	S	18-Jan-16	28-Jan-16	Fired on Safe Release	Unexplained Discharge - No Mention of Safety Position	508634	F	Per Ilion - Replace TA & test @ n/c	
12962	700	not avail.	REM	22-250	5-Dec-77	N	S	20-Jan-16	29-Jan-16	Fired on Safe Release	Altered Adjustments or Components	508748	F	Per Ilion - Replace TA & test @ n/c

RAC001256

Confidential

								Unexplained Discharge - No Mention of Safety	Could Not Duplicate				
12964	700	25797	280 REM	28-Feb-01	N	S	20-Jan-16	28-Jan-16	Position	Concern	508804	F	Per Ilion - Replace TA & test @ n/c
12959	700	26285	7MM-08 REM	20-May-10	N	S	20-Jan-16	20-Jan-16	Other - Firearms - XMP Update	Could Not Duplicate	508802	F	Per Ilion - Replace TA & test @ n/c
12961	783	85781	308 WIN	27-Aug-15	N	S	20-Jan-16	20-Jan-16	Fired on Bolt Closing	Broken or Missing Parts	508750	F	Check over completely, repair as needed, and test at no charge
12960	700	not avail.	3006 SPRG	26-Jun-78	N	S	20-Jan-16	9-Feb-16	Unexplained Discharge - No Mention of Safety	Could Not Duplicate	508803	F	Per Ilion - Replace TA & test @ n/c
12954	710	27410	3006 SPRG	22-Jun-06	Y	S	20-Jan-16	5-Feb-16	Fired With Safe ON	Altered Adjustments or Components	508844	F	Per Ilion - Replace TA & test @ n/c
12957	700	25773	3006 SPRG	10-Sep-90	N	S	20-Jan-16	20-Jan-16	Fired on Bolt Closing	Could Not Duplicate	508749	F	Per Ilion - Replace TA & test @ n/c
12958	788	not avail.	243 WIN	1-Jun-68	Y	S	20-Jan-16	20-Jan-16	Fired on Bolt Closing	Could Not Duplicate	508751	F	Per Ilion - Check over & clean
12970	700	27267	270 WIN	8-Feb-07	N	S	25-Jan-16	10-Feb-16	Fired on Safe Release	Could Not Duplicate	508912	F	Per Ilion - Replace TA & test @ n/c
12973	700	25793	3006 SPRG	23-Jan-03	N	S	25-Jan-16	11-Feb-16	Fired on Safe Release	Could Not Duplicate	508910	F	Per Ilion - Replace TA & test @ n/c
12972	710	27414	300 WIN MA	14-Jul-05	Y	S	25-Jan-16	23-Feb-16	Unexplained Discharge - No Mention of Safety	Could Not Duplicate	509005	F	Per Ilion - Replace TA & test @ n/c
12981	887	82500	12 GA	5-Mar-10	Y	S	25-Jan-16	10-Feb-16	Fired on Bolt Closing	Concern	509012	F	Per Ilion - Repair at n/c
12979	700	26189	22-250 REM	20-Dec-04	N	S	25-Jan-16	25-Jan-16	Unexplained Discharge - No Mention of Safety	Could Not Duplicate	509002	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12980	700	25606	25-06 REM	13-Nov-91	N	S	25-Jan-16	25-Jan-16	Unexplained Discharge - No Mention of Safety	Could Not Duplicate	509003	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12971	700	N/A	3006 SPRG	15-Sep-75	N	S	25-Jan-16	25-Jan-16	Unexplained Discharge - No Mention of Safety	Could Not Duplicate	508867	F	Per Ilion, check over completely, repair as needed and test at no charge
12978	700	27480	7MM REM MA	27-Mar-00	N	S	25-Jan-16	25-Jan-16	Unexplained Discharge - No Mention of Safety	Could Not Duplicate	509004	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12976	770	85631	7MM-08 REM	30-Jul-12	N	S	25-Jan-16	25-Jan-16	Fired on Bolt Opening	Concern	508909	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12974	887	82540	12 GA	31-Jul-13	N	S	25-Jan-16	25-Jan-16	Fired Out of Battery	Concern	508866	F	Consumer Service is replacing gun
12988	700	not avail.	270 WIN	27-Oct-70	N	PD/S	27-Jan-16	23-Feb-16	Fired on Safe Release	Concern	509110	F	Per Ilion - Replace TA & test @ n/c
12987	770	85632	270 WIN	9-Aug-12	Y	PD/S	27-Jan-16	25-Feb-16	Fired on Safe Release	Concern	509077	F	Repair @ n/c
12985	700	not avail.	3006 SPRG	20-Mar-73	N	S	27-Jan-16	29-Feb-16	Fired on Safe Release	Altered Adjustments or Components	509109	F	Per Ilion - Replace TA & test @ n/c
12986	700	25813	3006 SPRG	11-Sep-96	N	S	27-Jan-16	23-Feb-16	Fired on Bolt Closing	AFT MKT TRIGGER ASSM	509054	F	Per Ilion - Replace TA & test @ n/c

RAC001257

Confidential

12984	700	26323	7MM SAUM	19-May-03	N	S	27-Jan-16	1-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509055	F	Per Ilion - Replace TA & test @ n/c
12994	700	N/A	243 WIN	14-Nov-75	N	S	27-Jan-16	27-Jan-16	Fired With Safe ON	Could Not Duplicate Concern	509072	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12996	700	N/A	25-06 REM	9-Feb-71	N	S	27-Jan-16	27-Jan-16	Fired on Safe Release	Altered Adjustments or Components	509071	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12991	700	not avail.	3006 SPRG	4-Mar-82	N	S	27-Jan-16	27-Jan-16	Safety not working properly	Could Not Duplicate Concern	509073	F	Per Ilion - Replace TA & test @ n/c - goodwill
12997	700	N/A	6MM REM	5-Apr-74	N	S	27-Jan-16	27-Jan-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	509130	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12992	700	27480	7MM REM MA	1-May-02	N	S	27-Jan-16	27-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509131	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12993	SEVEN	N/A	308 WIN	31-Aug-88	N	S	27-Jan-16	27-Jan-16	Fired on Bolt Closing	Altered Adjustments or Components	509132	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
13005	597	26581	22 WMR	4-Sep-01	N	S	29-Jan-16	3-Feb-16	Fired Out of Battery	Could Not Duplicate Concern	509186	F	Per Ilion, check over completely, repair as needed, and test at a 50% discount.
13003	700	not avail.	243 WIN	1-Sep-74	N	S	29-Jan-16	23-Feb-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509247	F	Per Ilion - Replace TA & test @ n/c
13004	700	not avail.	243 WIN	25-Apr-78	N	S	29-Jan-16	9-Feb-16	Fired on Bolt Opening	Could Not Duplicate Concern	509204	F	Per Ilion - Replace TA & test @ n/c
13007	700	not avail.	300 WIN	31-Jan-73	N	S	29-Jan-16	8-Feb-16	Fired on Bolt Closing	Altered Adjustments or Components	509205	F	Per Ilion - Replace TA & test @ n/c
13006	700	not avail.	3006 SPRG	13-Mar-69	N	S	29-Jan-16	9-Feb-16	Fired on Safe Release	Could Not Duplicate Concern	509248	F	Per Ilion - Replace TA & test @ n/c
13000	887	82540	12 GA	7-May-12	Y	S	29-Jan-16	23-Feb-16	Fired With Safe ON	Could Not Duplicate Concern	509250	F	Per Ilion - Repair at n/c
13002	H&R Handi-Rifle	72430	300 BLACKO	12-Apr-13	N	S	29-Jan-16	29-Jan-16	Delayed Firing - Firearms	Could Not Duplicate Concern	509174	F	Per Ilion, check over completely, repair as needed, and test at no charge
13017	700	not avail.	6MM REM	27-Oct-77	N	S	2-Feb-16	24-Feb-16	Fired on Safe Release	Could Not Duplicate Concern	509311	F	Per Ilion - Replace TA & test @ n/c
13014	700	not avail.	7MM REM MA	30-Aug-78	N	S	2-Feb-16	25-Feb-16	Fired on Safe Release	Could Not Duplicate Concern	509308	F	Per Ilion - Replace TA & test @ n/c
13018	700	not avail.	8MM REM MA	25-Jun-77	N	S	2-Feb-16	24-Feb-16	Fired on Safe Release	Could Not Duplicate Concern	509324	F	Per Ilion - Replace TA & test @ n/c
13021	1187	29674	12 GA	11-Dec-95	N	S	2-Feb-16	2-Feb-16	Fired on Bolt Closing	Could Not Duplicate Concern	509313	F	Check over completely, repair as needed, and test at no charge
13013	700 ML	27588	50 CAL	8-Jul-98	N	S	2-Feb-16	25-Feb-16	Fired on Safe Release	Could Not Duplicate Concern	509309	F	Per Ilion - Replace TA & test @ n/c
13015	700	not avail.	243 WIN	17-Nov-00	N	S	2-Feb-16	2-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509307	F	Per Ilion - Replace TA & test @ n/c
13177	700	not avail.	270 WIN	2-Apr-81	N	S	2-Feb-16	9-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	509306	F	Per Ilion - Replace TA & test @ n/c

RAC001258

Confidential

13029	700	85433	223 REM	14-Feb-12	N	S	4-Feb-16	24-Feb-16	Fired on Safe Release	Could Not Duplicate Concern	509408	F	Per Ilion - Replace TA & test @ n/c
13026	700	not avail.	25-06 REM	5-Jan-72	N	S	4-Feb-16	25-Feb-16	Fired on Bolt Opening	Could Not Duplicate Concern	509410	F	Per Ilion - Replace TA & test @ n/c
13027	700	not avail.	3006 SPRG	27-Nov-68	N	S	4-Feb-16	25-Feb-16	Fired With Safe ON	Could Not Duplicate Concern	509409	F	Per Ilion - Replace TA & test @ n/c
13033	700	not avail.	7MM REM	26-Apr-79	N	S	4-Feb-16	9-Feb-16	Fired on Bolt Closing	Could Not Duplicate Concern	509430	F	Per Ilion - Replace TA & test @ n/c
13032	721	not avail.	3006 SPRG	1-Feb-53	Y	S	4-Feb-16	9-Feb-16	Fired on Safe Release	Altered Adjustments or Components	509429	F	Per Ilion - Replace TA & test @ n/c
13028	770	85652	270 WIN	15-Oct-13	Y	S	4-Feb-16	4-Feb-16	Fired on Bolt Opening	Could Not Duplicate Concern	509377	F	Per Ilion - Replace TA & test @ n/c
13030	700	26080	7MM WEATHE	21-Jul-92	N	S	4-Feb-16	1-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509407	F	Per Ilion - Replace TA & test @ n/c
13034	783	85837	308 WIN	13-Sep-13	N	S	4-Feb-16	*	Fired on Bolt Closing	Other - Unexamined		F	
13045	SEVEN	24741	7MM-08 REM	20-Feb-96	N	PD/S	8-Feb-16	26-Feb-16	Fired on Safe Release	Altered Adjustments or Components	509520	F	Replace TA & test @ n/c
13037	700	not avail.	270 WIN	8-Jan-85	N	S	8-Feb-16	29-Feb-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	509572	F	Per Ilion - Replace TA & test @ n/c
13046	700	27478	3006 SPRG	27-Oct-95	N	S	8-Feb-16	26-Feb-16	Fired on Safe Release	Could Not Duplicate Concern	509517	F	Per Ilion - Replace TA & test @ n/c
13049	700	not avail.	3006 SPRG	24-Jul-78	N	S	8-Feb-16	25-Feb-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	509570	F	Per Ilion - Replace TA & test @ n/c
13052	700	not avail.	3006 SPRG	8-Jun-73	N	S	8-Feb-16	25-Feb-16	Fired With Safe ON	Could Not Duplicate Concern	509552	F	Per Ilion - Replace TA & test @ n/c
13038	700	25775	308 WIN	3-Aug-90	N	S	8-Feb-16	29-Feb-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509573	F	Per Ilion - Replace TA & test @ n/c
13043	700	not avail.	7MM REM	20-Mar-72	N	S	8-Feb-16	26-Feb-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509521	F	Per Ilion - Replace TA & test @ n/c
13048	770	85632	270 WIN	10-Dec-08	Y	S	8-Feb-16	29-Feb-16	Fired on Safe Release	Altered Adjustments or Components	509571	F	Per Ilion - Replace TA & test @ n/c
13047	700	not avail.	243 WIN	20-Oct-77	N	S	8-Feb-16	4-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509566	F	Per Ilion - Replace TA & test @ n/c
13040	700	25789	25-06 REM	24-Jan-86	N	S	8-Feb-16	7-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509524	F	Per Ilion - Replace TA & test @ n/c
13044	700	not avail.	25-06 REM	6-Jun-78	N	S	8-Feb-16	4-Mar-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	509523	F	Per Ilion - Replace TA & test @ n/c
13036	700	25773	3006 SPRG	25-Nov-85	N	S	8-Feb-16	1-Mar-16	Fired on Safe Release	Altered Adjustments or Components	509574	F	Per Ilion - Replace TA & test @ n/c
13042	700	25773	3006 SPRG	18-Oct-96	N	S	8-Feb-16	4-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509522	F	Per Ilion - Replace TA & test @ n/c

RAC001259

Confidential

13039	887	82500	12 GA	20-Dec-13	Y	S	8-Feb-16	7-Mar-16	Fired With Safe ON	Could Not Duplicate Concern	509493	F	Call Center issued a refund to customer
13051	1187	25337	12 GA	27-Sep-00	N	S	8-Feb-16	7-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	509553	F	Per Ilion - Repair at n/c - goodwill
13053	1100	N/A	12 GA	11-Nov-71	N	S	10-Feb-16	10-Feb-16	Fired With Safe ON	Other - Unspecified or Undetermined - Firearms	509665	F	Per Ilion quote to check over completely, repair, and test at a 50% discount
13059	700	not avail.	3006 SPRG	12-Jun-79	N	S	10-Feb-16	1-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	509666	F	Per Ilion - Replace TA & test @ n/c
13055	700	27343	7MM REM MA	23-May-05	N	S	10-Feb-16	8-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509662	F	Per Ilion - Replace TA & test @ n/c
13057	700	27125	7MM REM MA	1-Feb-06	N	S	10-Feb-16	8-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	509663	F	Per Ilion - Replace TA & test @ n/c
13060	700	not avail.	7MM REM MA	19-Oct-70	N	S	10-Feb-16	8-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509664	F	Per Ilion - Replace TA & test @ n/c
13056	40-X	27225	308 WIN	10-Apr-07	N	S	10-Feb-16	1-Mar-16	Fired on Bolt Closing	Other - Unspecified or Undetermined - Firearms	509667	F	Per Ilion - Replace TA & test @ n/c
13066	582	29856	22 RF	17-May-79	Y	S	11-Feb-16	11-Feb-16	Fired on Safe Release	Improper Maintenance	509724	F	Per Ilion - Check over, clean, test @ n/c
13096	597	26536	17 HMR	20-Nov-02	N	PD/S	11-Feb-16	7-Mar-16	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	510265	F	Consumer Service is refunding purchase price
13064	700	26033	270 WIN	12-Oct-01	N	S	11-Feb-16	2-Mar-16	Fired on Bolt Closing	Could Not Duplicate Concern	509703	F	Per Ilion - Replace TA & test @ n/c
13065	700	not avail.	3006 SPRG	13-Mar-75	N	S	11-Feb-16	9-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509705	F	Per Ilion - Replace TA & test @ n/c
13067	700	not avail.	3006 SPRG	4-Apr-75	N	S	11-Feb-16	2-Mar-16	Fired on Bolt Closing	Could Not Duplicate Concern	509701	F	Per Ilion - Replace TA & test @ n/c
13068	700	85375	7MM REM MA	10-Nov-11	N	S	11-Feb-16	2-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509706	F	Per Ilion - Replace TA & test @ n/c
13082	870	25583	20 GA	22-Oct-93	N	S	15-Feb-16	15-Feb-16	Fired With Safe ON	Could Not Duplicate Concern	509842	F	Per Ilion, check over completely, repair, and test at no charge
13075	PARDNER PUMP	72262	20 GA	23-Jul-15	N	S	15-Feb-16	15-Feb-16	Fired With Safe ON	Other - Unspecified or Undetermined - Firearms	509820	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13078	700	not avail.	270 WIN	1-Apr-67	N	S	15-Feb-16	2-Mar-16	Fired on Bolt Closing	Altered Adjustments or Components	509838	F	Per Ilion - Replace TA & test @ n/c
13074	700	not avail.	3006 SPRG	2-Jul-74	N	S	15-Feb-16	15-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509795	F	Per Ilion - Replace TA & test @ n/c
13077	700	not avail.	3006 SPRG	21-Oct-81	N	S	15-Feb-16	15-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	509792	F	Per Ilion - Replace TA & test @ n/c
13083	700	not avail.	308 WIN	1-Nov-67	N	S	15-Feb-16	2-Mar-16	Fired on Bolt Closing	Could Not Duplicate Concern	509843	F	Per Ilion - Replace TA & test @ n/c

RAC001260

Confidential

13079	700	not avail.	7MM REM MA		23-Oct-79	N	S	15-Feb-16	9-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509794	F	Per Ilion - Replace TA & test @ n/c
13076	710	27404	270 WIN	28-Nov-01	Y	S		15-Feb-16	9-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	509793	F	Replace w/85844 in exchange
13080	770	85632	270 WIN	21-Oct-09	Y	S	15-Feb-16	5-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509844	F	Replace w/85844 in exchange	
13091	700	84019	257 WBY MA	17-Dec-08	N	PD/S	17-Feb-16	9-Mar-16	Fired With Safe ON	Could Not Duplicate Concern	509962	F	Replace TA & test @ n/c	
13093	700	25787	243 WIN	20-Apr-95	N	S	17-Feb-16	10-Mar-16	Fired on Bolt Opening	Could Not Duplicate Concern	509907	F	Per Ilion - Replace TA & test @ n/c	
13097	700	25771	270 WIN	21-Sep-87	N	S	17-Feb-16	8-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	509949	F	Per Ilion - Replace TA & test @ n/c	
13089	700	not avail.	3006 SPRG	29-May-74	N	S	17-Feb-16	24-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	509964	F	Per Ilion - Replace TA & test @ n/c	
13095	700	25859	3006 SPRG	28-Oct-95	N	S	17-Feb-16	15-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509950	F	Per Ilion - Replace TA & test @ n/c	
13098	700	not avail.	3006 SPRG	28-Feb-79	N	S	17-Feb-16	4-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	509905	F	Per Ilion - Replace TA & test @ n/c	
13090	700	not avail.	7MM REM MA	3-Mar-69	N	S	17-Feb-16	17-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509963	F	Per Ilion - Replace TA & test @ n/c	
13094	710	27408	270 WIN	11-Nov-05	Y	S	17-Feb-16	17-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	509906	F	Per Ilion - Replace TA & test @ n/c	
13092	700	20000			N	PD/S	17-Feb-16	*	Fired on Bolt Opening	Other - Unexamined		F		
13104	660	N/A	308 WIN	1-Aug-69	Y	S	19-Feb-16	19-Feb-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	510023	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge	
13105	700	25791	270 WIN	13-Dec-89	N	S	19-Feb-16	19-Feb-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510014	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge	
13101	700	26129	3006 SPRG	23-Apr-01	N	S	19-Feb-16	19-Feb-16	Fired on Safe Release	Could Not Duplicate Concern	509990	F	Per Ilion - Replace TA & test @ n/c	
13109	700	N/A	3006 SPRG	13-Sep-71	N	S	19-Feb-16	19-Feb-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510013	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge	
13102	770	85632	270 WIN	16-Feb-12	Y	S	19-Feb-16	19-Feb-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510011	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge	
13103	710	27410	3006 SPRG	10-Aug-04	Y	S	19-Feb-16	24-Mar-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	510012	F	Replace w/85846 in exchange, Ck for \$54 (transfer fee)	

RAC001261

Confidential

13110	700	27095	3006 SPRG	27-Aug-10	N	PD/S	19-Feb-16	11-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510024	F	Per Release - Reimburse for truck repair & tire replacement (\$1,634.83)
13118	700	not avail.	3006 SPRG	22-Aug-84	N	S	23-Feb-16	23-Feb-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	510077	F	Per Ilion - Replace TA & test @ n/c
13115	870	25098	12 GA	6-Nov-09	N	S	23-Feb-16	23-Feb-16	Jamming/Feeding issues	Other - Unspecified or Undetermined - Firearms	510141	F	Ilion repaired at n/c - goodwill
13123	700	not avail.	270 WIN	5-May-77	N	PD/S	23-Feb-16	10-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	510119	F	Per Ilion - Replace TA & test @ n/c
13117	700	not avail.	25-06 REM	19-Mar-81	N	S	23-Feb-16	16-Mar-16	Fired on Bolt Opening	Altered Adjustments or Components	510116	F	Per Ilion - Replace TA & test @ n/c
13121	700	26096	300 RUM	21-Feb-00	N	S	23-Feb-16	22-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510079	F	Per Ilion - Replace TA & test @ n/c
13119	700	25955	3006 SPRG	22-May-02	N	S	23-Feb-16	10-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510117	F	Per Ilion - Replace TA & test @ n/c
13122	700	not avail.	3006 SPRG	1-Sep-74	N	S	23-Feb-16	17-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	510078	F	Per Ilion - Replace TA & test @ n/c
13120	700	not avail.	7MM REM MA	24-Oct-75	N	S	23-Feb-16	22-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510118	F	Per Ilion - Replace TA & test @ n/c
13130	600	not avail.	6MM REM	15-Aug-77	Y	S	25-Feb-16	25-Feb-16	Fired on Bolt Closing	Could Not Duplicate Concern	510271	F	Per Ilion - Replace TA & test @ n/c
13133	700	25803	7MM REM MA	17-Nov-92	N	S	25-Feb-16	25-Feb-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510198	F	Per Ilion - Replace TA & test @ n/c
13134	SEVEN	24741	7MM-08 REM	7-Oct-96	N	S	25-Feb-16	25-Feb-16	Fired on Bolt Closing	Could Not Duplicate Concern	510181	F	Per Ilion - Replace TA & test @ n/c
13137	700	not avail.	243 WIN	5-Apr-79	N	S	25-Feb-16	28-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510243	F	Per Ilion - Replace TA & test @ n/c
13131	700	not avail.	7MM REM MA	1-Nov-74	N	S	25-Feb-16	16-Mar-16	Fired on Bolt Closing	Could Not Duplicate Concern	510246	F	Per Ilion - Replace TA & test @ n/c
13145	700	not avail.	270 WIN	30-Apr-76	N	S	1-Mar-16	17-Mar-16	Fired on Bolt Closing	Altered Adjustments or Components	510332	F	Per Ilion - Replace TA & test @ n/c
13141	700	not avail.	300 WIN MA	16-Aug-74	N	S	1-Mar-16	2-Mar-16	Fired on Bolt Closing	Altered Adjustments or Components	510298	F	Per Ilion - Replace TA & test @ n/c
13142	710	27408	270 WIN	3-Sep-04	Y	S	1-Mar-16	30-Mar-16	Fired on Bolt Closing	Altered Adjustments or Components	510300	F	Replace w/85844 in exchange
13140	770	85637	243 WIN	20-Jan-09	Y	S	1-Mar-16	2-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	510337	F	Per Ilion - Replace TA & test @ n/c
13146	870	25100	12 GA	8-Feb-13	N	S	1-Mar-16	1-Mar-16	Fired Out of Battery	Could Not Duplicate Concern	510323	F	Per Ilion, check over completely, repair, and test at no charge
13150	700	84600	223 REM	9-Aug-11	N	PD/S	2-Mar-16	30-Mar-16	Fired on Bolt Closing	Could Not Duplicate Concern	510859	F	Replace TA & test @ n/c
13158	597	26514	17 HMR	27-Dec-04	N	PD/S	3-Mar-16	3-Mar-16	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	510400	F	Per Ilion, converting to 22 WMR as requested by consumer

RAC001262

Confidential

13166	660	not avail.	308 WIN	1-Dec-68	Y	S	3-Mar-16	8-Mar-16	Fired on Safe Release	Improper Maintenance	510468	F	Per Ilion - Repair at n/c
13159	700	29709	270 WIN	29-Sep-04	N	S	3-Mar-16	8-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	510401	F	Per Ilion - Replace TA & test @ n/c
13153	700	25807	300 WIN MA	22-Mar-90	N	S	3-Mar-16	3-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510424	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13156	700	25793	3006 SPRG	7-Oct-91	N	S	3-Mar-16	3-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510423	F	Per Ilion - Replace TA & test @ n/c
13157	700	not avail.	3006 SPRG	1-Feb-68	N	S	3-Mar-16	8-Mar-16	Fired on Bolt Closing	Improper Maintenance	510404	F	Per Ilion - Replace TA & test @ n/c
13160	710	27410	3006 SPRG	18-Mar-03	Y	S	3-Mar-16	8-Mar-16	Fired on Bolt Closing	Improper Maintenance	510483	F	Replace in exchange with Ramax 85846 at no charge
13165	887	82578	12 GA	12-Feb-14	Y	S	3-Mar-16	3-Mar-16	Safety not working properly	Could Not Duplicate Concern	510411	F	Per Ilion, check over completely, repair, and test at no charge
13169	700	N/A	3006 SPRG	2-May-74	N	S	7-Mar-16	7-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510554	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13172	700	26287	3006 SPRG	20-Apr-01	N	S	7-Mar-16	9-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510553	F	Per Ilion - Replace TA & test @ n/c
13174	700	N/A	3006 SPRG	21-Mar-69	N	S	7-Mar-16	7-Mar-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	510552	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13173	788	not avail.	243 WIN	26-Jan-79	Y	S	7-Mar-16	9-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	510595	F	Per Ilion - Check over, clean, test @ n/c - goodwill
13170	700 ML	27572	50 CAL	16-Sep-97	N	S	7-Mar-16	9-Mar-16	Unexplained Discharge - No Mention of Safety Position	Broken or Missing Parts	510551	F	Per Ilion - Replace TA & test @ n/c
13171	78 Sportsman	not avail.	270 WIN	9-Apr-88	Y	PI/S	7-Mar-16	14-Apr-16	Fired on Safe Release	Other - Unspecified or Undetermined - Firearms	510610	F	Per Ilion - Replace TA & test @ n/c
13178	770	85637	243 WIN	4-Nov-11	Y	PI/S	8-Mar-16	*	Fired on Safe Release	Other - Unexamined		F	
13187	700	25714	223 REM	16-May-13	N	S	10-Mar-16	11-Mar-16	Fired on Bolt Closing	Other - Unspecified or Undetermined - Firearms	510653	F	Per Ilion - Replace TA & test @ n/c
13182	700	27092	243 WIN	11-May-10	N	S	10-Mar-16	11-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	510758	F	Per Ilion - Replace TA & test @ n/c
13184	700	84170	243 WIN	13-Nov-06	N	S	10-Mar-16	10-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510710	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13191	700	not avail.	243 WIN	28-Apr-71	N	S	10-Mar-16	11-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510706	F	Per Ilion - Replace TA & test @ n/c
13188	700	29712	3006 SPRG	25-Jun-92	N	S	10-Mar-16	10-Mar-16	Fired on Bolt Closing	Could Not Duplicate Concern	510685	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge

RAC001263

Confidential

13189	700	not avail.	3006 SPRG	28-Jul-76	N	S	10-Mar-16	11-Mar-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	510707	F	Per Ilion - Replace TA & test @ n/c
13186	700	N/A	308 WIN	12-Dec-80	N	S	10-Mar-16	10-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	510709	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13183	700	25803	7MM REM MA	9-Nov-95	N	S	10-Mar-16	10-Mar-16	Fail to Fire	Could Not Duplicate Concern	510637	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13185	700	not avail.	270 WIN	29-Jan-73	N	PD/S	10-Mar-16	8-Apr-16	Fired on Safe Release	Altered Adjustments or Components	510708	F	Per Ilion - Replace TA & test @ n/c
13192	R-25	60032	308 WIN	12-Jul-11	N	PD/S	10-Mar-16	4-Apr-16	Fired on Bolt Closing	Could Not Duplicate Concern	511170	F	Repair @ n/c - goodwill gesture
13193	700	85539	223 REM	28-Dec-12	N	S	11-Mar-16	22-Mar-16	Dissatisfied with Service - Firearms	Could Not Duplicate Concern	511159	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13194	700	N/A	7MM REM MA	1-Oct-68	N	S	14-Mar-16	14-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	510875	F	Per Ilion - Quote to repair
13196	700	N/A	7MM REM MA	5-Mar-70	N	S	14-Mar-16	14-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	510862	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13197	710	27410	3006 SPRG	11-Apr-02	Y	S	14-Mar-16	14-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	510861	F	Replace in exchange with Ramac 85846 at no charge
13198	710	27410	3006 SPRG	30-May-03	Y	S	14-Mar-16	14-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	510863	F	Replace in exchange with Ramac 85846 at no charge
13204	700	N/A	270 WIN	26-Apr-76	N	S	16-Mar-16	16-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510897	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13206	770	85681	243 WIN	30-Sep-09	Y	S	16-Mar-16	16-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510949	F	Per Ilion - Replace TA & test @ n/c
13205	770	85636	300 WIN MA	4-Oct-07	Y	S	16-Mar-16	23-Mar-16	Fired on Bolt Closing	Altered Adjustments or Components	510940	F	CSR in the Call Center replaced rifle through SNC
13207	770	85632	270 WIN	31-May-13	Y	S	16-Mar-16	13-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510948	F	Per Ilion - Replace TA & test @ n/c
13212	700	not avail.	308 WIN	22-Apr-75	N	S	18-Mar-16	22-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	510989	F	Per Ilion - Replace TA & test @ n/c
13213	700	N/A	7MM REM MA	1-Sep-74	N	S	18-Mar-16	18-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511034	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13211	700	25793	3006 SPRG	18-Sep-13	N	S	18-Mar-16	18-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511032	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge

RAC001264

Confidential

13218	700	N/A	7MM REM MA	1-Oct-64	N	S	22-Mar-16	22-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511152	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13217	700	25855	7MM-08 REM	18-Mar-03	N	S	22-Mar-16	23-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511153	F	Per Ilion - Replace TA & test @ n/c
13216	VERSA MAX	81045	12 GA	5-Mar-14	N	S	22-Mar-16	22-Mar-16	Blowback in Face	Could Not Duplicate Concern	511157	F	Per Ilion, check over completely, repair, and test at no charge
13221	700	N/A	270 WIN	25-Jan-79	N	S	24-Mar-16	24-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511263	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13224	700	N/A	270 WIN	12-Sep-77	N	S	24-Mar-16	24-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511262	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13225	700	N/A	3006 SPRG	31-Mar-75	N	S	24-Mar-16	24-Mar-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	511272	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13229	700	N/A	7MM EXP RE	5-Oct-79	N	S	24-Mar-16	24-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511259	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13230	710	27408	270 WIN	11-Mar-03	Y	S	24-Mar-16	24-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	511258	F	Per Ilion, replace in exchange with Ramac 85844 at no charge
13226	710	27412	7MM REM MA	15-Feb-06	Y	S	24-Mar-16	24-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	511257	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13223	SEVEN	24787	223 REM	5-Mar-02	N	S	24-Mar-16	24-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511261	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13228	SEVEN	24787	223 REM	5-Mar-02	N	S	24-Mar-16	24-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511260	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13231	700	25739	308 WIN	14-Nov-14	N	S	24-Mar-16	18-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	511913	F	Per Ilion - Replace TA & test @ n/c
13238	700	N/A	270 WIN	22-Aug-74	N	S	31-Mar-16	31-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511496	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13239	700	25771	270 WIN	16-Mar-84	N	S	31-Mar-16	31-Mar-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	511497	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13237	700	N/A	3006 SPRG	27-Oct-72	N	S	31-Mar-16	31-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	511495	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13243	700	27478	3006 SPRG	6-Jul-00	N	S	31-Mar-16	31-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511499	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge

RAC001265

Confidential

13245	700	N/A	3006 SPRG	31-Aug-71	N	S	31-Mar-16	31-Mar-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	511500	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13240	700	N/A	7MM REM MA	2-Jun-75	N	S	31-Mar-16	31-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511498	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13247	RM380	96454	380 ACP	15-Oct-15	N	S	31-Mar-16	31-Mar-16	Fired on Bolt Closing	Could Not Duplicate Concern	511378	F	Per Ilion, check over completely, repair, and test at no charge
13255	700	not avail.	243 WIN	5-Dec-78	N	S	4-Apr-16	14-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	511610	F	Per Ilion - Replace TA & test @ n/c
13252	700	25851	270 WIN	16-Jun-98	N	S	4-Apr-16	4-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511606	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13254	700	27476	270 WIN	29-Oct-99	N	S	4-Apr-16	20-Apr-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	511605	F	Per Ilion - Replace TA & test @ n/c
13258	700	25630	270 WIN	5-Dec-88	N	S	4-Apr-16	4-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511607	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13259	700	26092	280 REM	29-Sep-92	N	S	4-Apr-16	4-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511604	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13257	700	N/A	3006 SPRG	1-Aug-68	N	S	4-Apr-16	4-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511608	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13253	700	26420	7MM REM MA	21-Aug-03	N	S	4-Apr-16	4-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511611	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13256	700	25855	7MM-08	6-May-98	N	S	4-Apr-16	4-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511612	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13260	SEVEN	24782	243 WIN	9-Apr-84	N	S	4-Apr-16	4-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511609	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13266	700	not avail.	243 WIN	15-May-72	N	PI/S	7-Apr-16	14-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	511793	F	Per Ilion - Replace TA & test @ n/c
13264	700	not avail.	243 WIN	11-Jan-79	N	S	7-Apr-16	13-Apr-16	Fired on Bolt Closing	Improper Maintenance	511795	F	Per Ilion - Replace TA & test @ n/c
13265	700	not avail.	3006 SPRG	22-Oct-73	N	S	7-Apr-16	14-Apr-16	Fired on Bolt Closing	Could Not Duplicate Concern	511792	F	Per Ilion - Replace TA & test @ n/c
13273	700	N/A	243 WIN	9-Sep-88	N	S	8-Apr-16	8-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511791	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13274	700	N/A	270 WIN	28-Sep-82	N	S	8-Apr-16	8-Apr-16	Fired on Bolt Closing	Altered Adjustments or Components	511720	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13269	700	not avail.	3006 SPRG	4-Aug-71	N	S	8-Apr-16	13-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	511789	F	Per Ilion - Replace TA & test @ n/c

RAC001266

Confidential

13275	700	N/A	3006 SPRG	8-May-72	N	S	8-Apr-16	8-Apr-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	511705	F	Per ilion, replace trigger, repair, check over completely, and test at no charge
13270	700	not avail.	6MM REM	14-Apr-69	N	S	8-Apr-16	13-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	511790	F	Per ilion - Replace TA & test @ n/c
13272	700	N/A	7MM REM MA	1-Dec-66	N	S	8-Apr-16	8-Apr-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	511794	F	Per ilion, replace trigger, repair, check over completely, and test at no charge
13268	710	27410	3006 SPRG	19-Oct-05	Y	S	8-Apr-16	8-Apr-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	511788	F	Per ilion, replace trigger, repair, check over completely, and test at no charge
13271	870	25587	12 GA	13-Feb-02	N	S	8-Apr-16	8-Apr-16	Delayed Firing - Firearms	Other - Unspecified or Undetermined - Firearms	511634	F	Per ilion, check over completely, repair, and test at no charge
13278	SEVEN	24741	7MM-08 REM	8-Mar-96	N	S	8-Apr-16	20-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511706	F	Per ilion - Replace TA & test @ n/c
13292	600	N/A	308 WIN	1-Jan-67	Y	S	12-Apr-16	12-Apr-16	Fired on Bolt Closing	Could Not Duplicate Concern	511910	F	Per ilion, replace trigger, repair, check over completely, and test at no charge
13282	700	N/A	22-250 REM	8-Apr-69	N	S	12-Apr-16	12-Apr-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	511956	F	Per ilion, replace trigger, repair, check over completely, and test at no charge
13284	700	25791	270 WIN	30-Oct-95	N	S	12-Apr-16	12-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511954	F	Per ilion, replace trigger, repair, check over completely, and test at no charge
13289	700	N/A	3006 SPRG	23-Jul-81	N	S	12-Apr-16	12-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511957	F	Per ilion, replace trigger, repair, check over completely, and test at no charge
13283	700	N/A	6MM REM	7-Jun-71	N	S	12-Apr-16	12-Apr-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	511959	F	Per ilion, replace trigger, repair, check over completely, and test at no charge
13287	700	86483	7.62MM	26-Jun-15	N	S	12-Apr-16	12-Apr-16	Fired on Safe Release	Altered Adjustments or Components	511945	F	Per ilion, replace trigger, repair, check over completely, and test at no charge
13296	700	27011	270 WIN	3-Nov-14	N	S	13-Apr-16	13-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511960	F	Per ilion, replace trigger, repair, check over completely, and test at no charge
13295	700	25793	3006 SPRG	14-Mar-85	N	S	13-Apr-16	13-Apr-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	511955	F	Per ilion, replace trigger, repair, check over completely, and test at no charge
13297	700	25709	308 WIN	5-Jan-96	N	S	13-Apr-16	13-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511962	F	Per ilion, replace trigger, repair, check over completely, and test at no charge
13298	700	N/A	7MM REM MA	23-Aug-78	N	S	13-Apr-16	13-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	511961	F	Per ilion, replace trigger, repair, check over completely, and test at no charge

RAC001267

Confidential

13294	770	85637	243 WIN	5-Dec-12	Y	S	13-Apr-16	13-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511958	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13309	700	85434	22-250 REM	28-Jun-12	N	S	15-Apr-16	20-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512060	F	Per Iliion - Replace TA & test @ n/c
13304	700	not avail.	243 WIN	6-Jun-77	N	S	15-Apr-16	21-Apr-16	Fired on Safe Release	Altered Adjustments or Components	512048	F	Per Iliion - Replace TA & test @ n/c
13301	700	not avail.	3006 SPRG	17-Jun-79	N	S	15-Apr-16	21-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512051	F	Per Iliion - Replace TA & test @ n/c
13311	700	N/A	3006 SPRG	14-Jan-88	N	S	15-Apr-16	15-Apr-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	512053	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13310	700	85435	308 WIN	17-Jun-09	N	S	15-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512046	F	Per Iliion - Replace TA & test @ n/c
13302	710	27416	243 WIN	8-Oct-06	Y	S	15-Apr-16	15-Apr-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	512026	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13308	710	27410	3006 SPRG	15-Feb-01	Y	S	15-Apr-16	27-Apr-16	Fired on Bolt Closing	Could Not Duplicate Concern	512050	F	Replace w/95846 in exchange
13303	770	85655	270 WIN	3-May-13	Y	S	15-Apr-16	15-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512049	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13299	887	82500	12 GA	18-Feb-14	Y	S	15-Apr-16	19-Apr-16	Fired on Bolt Closing	Could Not Duplicate Concern	511990	F	Per Iliion - Repair at n/c
13307	SEVEN	N/A	308 WIN	29-Aug-88	N	S	15-Apr-16	15-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512047	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13321	700	not avail.	22-250 REM	24-Apr-69	N	PI/S	18-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512105	F	Per Iliion - Replace TA & test @ n/c
13317	700	60560	22-250 REM	31-Aug-15	N	S	18-Apr-16	18-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512104	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13312	700	N/A	25-06 REM	31-Mar-78	N	S	18-Apr-16	18-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512109	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13327	700	25789	25-06 REM	4-Feb-86	N	S	18-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512099	F	Per Iliion - Replace TA & test @ n/c
13328	700	not avail.	25-06 REM	28-May-70	N	S	18-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512114	F	Per Iliion - Replace TA & test @ n/c

RAC001268

Confidential

13320	700	25771	270 WIN	25-Oct-91	N	S	18-Apr-16	18-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512119	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13324	700	N/A	270 WIN	13-Sep-77	N	S	18-Apr-16	18-Apr-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512101	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13314	700	27525	3006 SPRG	6-Jun-97	N	S	18-Apr-16	18-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512106	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13316	700	25773	3006 SPRG	27-May-86	N	S	18-Apr-16	18-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512111	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13323	700	25876	BMM REM MA	18-Feb-98	N	S	18-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512100	F	Per Iliion - Replace TA & test @ n/c
13315	710	27410	3006 SPRG	16-Feb-03	Y	S	18-Apr-16	29-Apr-16	Jar-Off - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	512108	F	Replace w/85842 in exchange
13319	710	27410	3006 SPRG	28-Mar-05	Y	S	18-Apr-16	18-Apr-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512107	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13329	770	85631	7mm-08 REM	26-Mar-09	Y	S	18-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512113	F	Per Iliion - Replace TA & test @ n/c
13326	SPORTSMAN 78	26162	270 WIN	23-May-84	Y	S	18-Apr-16	18-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	512097	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13325	710	27410	3006 SPRG	11-May-04	Y	S	18-Apr-16	23-May-16	Fired on Safe Release	Altered Adjustments or Components	512127	F	Replace w/85846 in exchange
13340	700	not avail.	3006 SPRG	23-Jun-78	N	PD/S	20-Apr-16	25-Apr-16	Fired on Safe Release	Altered Adjustments or Components	512191	F	Per Iliion - Replace TA & test @ n/c
13344	700	27131	204 RUGER	15-Feb-06	N	S	20-Apr-16	29-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512186	F	Per Iliion - Replace TA & test @ n/c
13341	700	not avail.	25-06 REM	25-Mar-77	N	S	20-Apr-16	26-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	512195	F	Per Iliion - Replace TA & test @ n/c
13343	700	not avail.	270 WIN	29-May-81	N	S	20-Apr-16	26-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512196	F	Per Iliion - Replace TA & test @ n/c
13346	700	not avail.	308 WIN	1-Jul-67	N	S	20-Apr-16	22-Apr-16	Fired on Safe Release	Altered Adjustments or Components	512211	F	Per Iliion - Replace TA & test @ n/c
13347	715	85807	243 WIN	22-Apr-08	Y	S	20-Apr-16	22-Apr-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512190	F	Per Iliion - Replace TA & test @ n/c
13338	870	25568	12 GA	25-Aug-92	N	S	20-Apr-16	22-Apr-16	Fired With Safe ON	Could Not Duplicate Concern	512118	F	Iliion repaired at n/c
13351	600	N/A	6.5MM REM	1-Aug-66	Y	S	21-Apr-16	21-Apr-16	Unexplained Discharge - No Mention of Safety Position	Broken or Missing Parts	512202	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge

RAC001269

Confidential

13359	700	27351	223 REM	18-Oct-05	N	S	22-Apr-16	22-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512281	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13356	700	not avail.	270 WIN	16-Mar-71	N	S	22-Apr-16	28-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512280	F	Per Ilion - Replace TA & test @ n/c
13354	700	25903	300 WBY MA	25-Jul-89	N	S	22-Apr-16	29-Apr-16	Fired on Bolt Closing	Could Not Duplicate Concern	512244	F	Per Ilion - Repair at n/c
13358	700	N/A	7MM REM MA	16-Mar-79	N	S	22-Apr-16	22-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512279	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13357	SEVEN	24779	243 WIN	17-Dec-02	N	S	22-Apr-16	22-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512282	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13353	DPMS LR-G2	60556	7.62X51	27-Oct-15	N	S	22-Apr-16	22-Apr-16	Fired on Bolt Closing	Could Not Duplicate Concern	512260	F	Consumer Service is refunding purchase price
13368	700	not avail.	243 WIN	1-Jun-67	N	PD/S	26-Apr-16	28-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	512378	F	Per Ilion - Replace TA & test @ n/c
13373	700	25813	3006 SPRG	25-Jun-02	N	PI/S	26-Apr-16	26-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512338	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13366	700	not avail.	22-250 REM	1-Dec-69	N	S	26-Apr-16	28-Apr-16	Delayed Firing - Firearms	Could Not Duplicate Concern	512377	F	Per Ilion - Replace TA & test @ n/c
13365	700	25771	270 WIN	30-Sep-97	N	S	26-Apr-16	28-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	512402	F	Per Ilion - Replace TA & test @ n/c
13371	700	N/A	270 WIN	1-Jul-67	N	S	26-Apr-16	26-Apr-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	512380	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13378	700	N/A	300 WIN MA	30-May-74	N	S	26-Apr-16	26-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512346	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13370	700	not avail.	3006 SPRG	1-Jan-67	N	S	26-Apr-16	28-Apr-16	Fired With Safe ON	Could Not Duplicate Concern	512376	F	Per Ilion - Replace TA @ n/c
13374	700	27478	3006 SPRG	11-Sep-96	N	S	26-Apr-16	28-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512333	F	Per Ilion - Replace TA & test @ n/c
13377	700	25634	3006 SPRG	31-Aug-87	N	S	26-Apr-16	26-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512334	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13372	700	25818	308 WIN	6-Mar-87	N	S	26-Apr-16	29-Apr-16	Fired on Bolt Closing	Could Not Duplicate Concern	512373	F	Per Ilion - Replace TA & test @ n/c
13379	700	N/A	6MM REM	30-Jun-77	N	S	26-Apr-16	26-Apr-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512332	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13369	700	not avail.	7MM REM MA	20-Jun-79	N	S	26-Apr-16	28-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	512375	F	Per Ilion - Replace TA & test @ n/c
13367	710	27410	3006 SPRG	17-Aug-06	Y	S	26-Apr-16	28-Apr-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512379	F	Per Ilion - Replace TA & test @ n/c

RAC001270

Confidential

13376	SEVEN	24781	260 REM	10-Jan-00	N	S	26-Apr-16	26-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512336	F	Per Iion, replace trigger, repair, check over completely, and test at no charge
13375	710	27410	3006 SPRG	16-Apr-01	Y	S	26-Apr-16	9-May-16	Fired on Bolt Closing	Altered Adjustments or Components	512369	F	Replace w/85846 in exchange
13394	700	85433	223 REM	29-May-12	N	S	27-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512453	F	Per Iion, replace trigger, repair, check over completely, and test at no charge
13380	700	29709	270 WIN	27-May-00	N	S	27-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512339	F	Per Iion, replace trigger, repair, check over completely, and test at no charge
13381	700	N/A	270 WIN	27-Aug-73	N	S	27-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512436	F	Per Iion, replace trigger, repair, check over completely, and test at no charge
13389	700	N/A	270 WIN	1-Jul-66	N	S	27-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512435	F	Per Iion, replace trigger, repair, check over completely, and test at no charge
13393	700	N/A	270 WIN	18-Feb-69	N	S	27-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512438	F	Per Iion, replace trigger, repair, check over completely, and test at no charge
13384	700	N/A	3006 SPRG	25-Apr-72	N	S	27-Apr-16	27-Apr-16	Fired on Safe Release	Altered Adjustments or Components	512457	F	Per Iion, replace trigger, repair, check over completely, and test at no charge
13387	700	N/A	3006 SPRG	3-Aug-73	N	S	27-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512431	F	Per Iion, replace trigger, repair, check over completely, and test at no charge
13388	700	N/A	3006 SPRG	5-Oct-73	N	S	27-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512433	F	Per Iion, replace trigger, repair, check over completely, and test at no charge
13395	700	N/A	6MM REM	23-Feb-73	N	S	27-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512434	F	Per Iion, replace trigger, repair, check over completely, and test at no charge
13382	700	25800	7MM-08 REM	26-Jan-94	N	S	27-Apr-16	29-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	512437	F	Per Iion - Replace TA & test @ n/c
13383	770	85632	270 WIN	5-Sep-12	Y	S	27-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512454	F	Per Iion, replace trigger, repair, check over completely, and test at no charge
13392	700 ML	27580	50 CAL	21-Jun-96	N	S	27-Apr-16	29-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	512432	F	Per Iion - Replace TA & test @ n/c
13385	710	27408	270 WIN	17-Aug-03	Y	S	27-Apr-16	9-May-16	Fired With Safe ON	Altered Adjustments or Components	512455	F	Replace w/85844 in exchange
13397	700	86477	7.62 NATO	13-Feb-13	N	S	28-Apr-16	28-Apr-16	Fired With Safe ON	Could Not Duplicate Concern	512458	F	Per Iion, replace trigger, repair, check over completely, and test at no charge
13403	770	85658	300 WIN MA	15-Mar-13	Y	S	2-May-16	2-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512510	F	Per Iion, replace trigger, repair, check over completely, and test at no charge

RAC001271

Confidential

13404	SEVEN	24788	308 WIN	17-Oct-84	N	S	2-May-16	2-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512509	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13405	700	N/A	243 WIN	30-Apr-71	N	S	2-May-16	2-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512514	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13406	700	26096	300 RUM	22-Feb-00	N	S	2-May-16	2-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512511	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13407	700	29696	338 WIN MA	4-Mar-97	N	S	2-May-16	2-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512508	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13409	700	N/A	270 WIN	1-Apr-74	N	S	2-May-16	2-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512515	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13410	710	27410	3006 SPRG	31-Aug-01	Y	S	2-May-16	11-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512518	F	Replace w/85846 in exchange
13411	700	25793	3006 SPRG	26-Apr-96	N	S	2-May-16	2-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	512517	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13414	700	N/A	3006 SPRG	10-Jun-78	N	S	2-May-16	10-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512516	F	Check over completely, repair as needed, and test at no charge
13415	700	N/A	243 WIN	28-Apr-69	N	S	2-May-16	2-May-16	Fired With Safe ON	Could Not Duplicate Concern	512488	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13417	700	N/A	270 WIN	5-Jun-72	N	S	3-May-16	3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512633	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13419	700	N/A	270 WIN	1-Oct-68	N	S	3-May-16	3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512573	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13420	700	N/A	3006 SPRG	28-Feb-79	N	S	3-May-16	3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512571	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13421	700	N/A	308 WIN	1-Aug-62	N	S	3-May-16	3-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512576	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13422	700	27478	3006 SPRG	28-Feb-03	N	S	3-May-16	3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512574	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13423	700	N/A	7MM EXP RE	21-Sep-79	N	S	3-May-16	3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512575	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge

RAC001272

Confidential

13424	700	26959	270 WIN	7-Nov-94	N	S	3-May-16	3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512572	F	Per Iilon, replace trigger, repair, check over completely, and test at no charge
13427	700	26158	22-250 REM	6-Feb-86	N	S	3-May-16	3-May-16	Fired With Safe ON	Altered Adjustments or Components	512578	F	Per Iilon, replace trigger, repair, check over completely, and test at no charge
13428	700	N/A	3006 SPRG	15-Jun-79	N	S	3-May-16	3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512577	F	Per Iilon, replace trigger, repair, check over completely, and test at no charge
13429	700	N/A	3006 SPRG	4-Mar-74	N	PD/S	3-May-16	3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512596	F	Per Iilon, replace trigger, repair, check over completely, and test at no charge
13430	700	27480	7MM REM M	28-Nov-01	N	S	3-May-16	3-May-16	Delayed Firing - Firearms	Could Not Duplicate Concern	512594	F	Per Iilon, replace trigger, repair, check over completely, and test at no charge
13425	870	25569	12 GA	20-Oct-15	N	S	3-May-16	*	Fired With Safe ON	Could Not Duplicate Concern	512570	F	Repair under warranty
13431	700	not avail.	7MM REM M	1-Dec-74	N	PD/S	4-May-16	10-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512676	F	Replace TA & test @ n/c
13432	700	26259	3006 SPRG	23-Oct-98	N	S	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512665	F	Per Iilon, replace trigger, repair, check over completely, and test at no charge
13433	770	85663	3006 SPRG	6-Oct-10	Y	S	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512664	F	Per Iilon, replace trigger, repair, check over completely, and test at no charge
13434	H&R HANDI RIFLE	72430	300 BLK OU	12-Apr-13	Y	S	4-May-16	4-May-16	Fail to Fire	Could Not Duplicate Concern	512693	F	Per Iilon, check over completely, repair, and test at no charge
13436	700	N/A	3006 SPRG	3-Mar-76	N	S	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512669	F	Per Iilon, replace trigger, repair, check over completely, and test at no charge
13437	700	N/A	3006 SPRG	22-Jul-75	N	S	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512675	F	Per Iilon, replace trigger, repair, check over completely, and test at no charge
13438	700	not avail.	270 WIN	23-Feb-72	N	S	4-May-16	6-May-16	Fired Bolt Closing	Could Not Duplicate Concern	512667	F	Per Iilon - Replace TA & test @ n/c
13439	700	N/A	243 WIN	26-May-76	N	S	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512671	F	Per Iilon, replace trigger, repair, check over completely, and test at no charge
13440	SPORTSMAN 78	N/A	3006 SPRG	23-May-88	Y	S	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512670	F	Per Iilon, replace trigger, repair, check over completely, and test at no charge
13441	700	N/A	3006 SPRG	9-Feb-88	N	S	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512679	F	Per Iilon, replace trigger, repair, check over completely, and test at no charge

RAC001273

Confidential

13442	700	N/A	3006 SPRG	1-Jan-65	N	S	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512673	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13443	770	85634	308 WIN	26-May-15	Y	S	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512668	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13444	700	27095	3006 SPRG	28-Dec-12	N	S	5-May-16	23-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512717	F	Per Iliion - Replace TA & test @ n/c
13445	700	N/A	25-06 REM	6-May-70	N	S	5-May-16	5-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512712	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13446	700	not avail.	3006 SPRG	27-Aug-71	N	S	5-May-16	13-May-16	Fired on Safe Release	Could Not Duplicate Concern	512733	F	Per Iliion - Replace TA & test @ n/c
13447	700	25851	270 WIN	7-Aug-97	N	S	5-May-16	12-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	512713	F	Per Iliion - Replace TA & test @ n/c
13448	700	not avail.	243 WIN	23-Oct-77	N	S	5-May-16	12-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512708	F	Per Iliion - Replace TA & test @ n/c
13449	700	27092	243 WIN	10-Sep-13	N	S	5-May-16	6-May-16	Other- Firearms - XMP Update	Could Not Duplicate Concern	512715	F	Per Iliion - Replace TA & test @ n/c
13450	770	85633	3006 SPRG	28-Jul-09	Y	S	5-May-16	23-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512716	F	Per Iliion - Replace TA & test @ n/c
13451	700	27512	22-250 REM	21-Nov-02	N	S	5-May-16	23-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512707	F	Per Iliion - Replace TA & test @ n/c
13452	700	N/A	22-250 REM	1-May-68	N	S	5-May-16	5-May-16	Fired on Safe Release	Could Not Duplicate Concern	512714	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13460	700	27476	270 WIN	21-Jan-99	N	S	9-May-16	9-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512794	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13461	770	85632	270 WIN	15-Sep-11	Y	S	9-May-16	23-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512795	F	Per Iliion - Replace TA & test @ n/c
13462	600	N/A	308 WIN	14-May-74	N	S	9-May-16	9-May-16	Fired on Bolt Closing	Altered Adjustments or Components	512750	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13463	700	N/A	6MM REM	26-Oct-77	N	S	9-May-16	9-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512792	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13464	700	N/A	3006 SPRG	26-Jan-77	N	S	9-May-16	9-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512793	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge

RAC001274

Confidential

13465	700 LH	N/A	270 WIN	20-Jan-81	N	S	9-May-16	9-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512791	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13467	700	N/A	308 WIN	23-Mar-76	N	S	9-May-16	9-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512797	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13469	700	N/A	270 WIN	7-May-73	N	S	9-May-16	9-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512790	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13470	700	not avail.	7MM REM M	25-May-76	N	S	9-May-16	17-May-16	Fired on Bolt Closing	Altered Adjustments or Components	512796	F	Per Iliion - Replace TA & test @ n/c
13471	700	not avail.	243 WIN	8-Apr-80	N	S	9-May-16	10-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512798	F	Per Iliion - Replace TA & test @ n/c
13472	870	81062	12 GA	14-Apr-14	N	PD/S	10-May-16	11-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	512861	F	Per Iliion - Repair & test at n/c
13473	700	N/A	270 WIN	24-Jun-76	N	S	10-May-16	10-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512837	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13474	700	85565	22-250 REM	2-Nov-12	N	S	10-May-16	10-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512838	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13475	700	N/A	270 WIN	1-Jan-80	N	S	10-May-16	10-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512839	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13476	700	N/A	308 WIN	5-Jun-75	N	S	10-May-16	10-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512840	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13477	700	26199	25-06 REM	8-Nov-96	N	S	10-May-16	10-May-16	Delayed Firing - Firearms	Could Not Duplicate Concern	512834	F	Per Iliion - Replace TA & test @ n/c
13478	700	not avail.	3006 SPRG	17-Sep-71	N	S	10-May-16	24-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512843	F	Per Iliion - Replace TA & test @ n/c
13479	700	84012	7MM-08 REM	29-Feb-12	N	S	10-May-16	23-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512841	F	Per Iliion - Replace TA & test @ n/c
13480	700	not avail.	308 WIN	1-Mar-67	N	S	10-May-16	11-May-16	Fired on Safe Release	Could Not Duplicate Concern	512842	F	Per Iliion - Replace TA & test @ n/c
13481	700	25857	280 REM	27-Jul-95	N	PD/S	10-May-16	23-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512862	F	Replace TA & test @ n/c
13482	700	N/A	300 WIN MA	7-Nov-80	N	S	12-May-16	12-May-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	512911	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13483	700	not avail.	22-250 REM	1-Mar-66	N	S	12-May-16	24-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512912	F	Per Iliion - Replace TA & test @ n/c

RAC001275

Confidential

13489	700	27095	3006 SPRG	8-Aug-11	N	S	12-May-16	13-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	512895	F	Per Iliion - Replace TA & test @ n/c
13490	710	27408	270 WIN	27-Oct-05	N	S	12-May-16	12-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512870	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13491	700	29692	7MM REM M	8-Apr-96	N	S	12-May-16	25-May-16	Fired on Safe Release	Could Not Duplicate Concern	512869	F	Per Iliion - Replace TA & test @ n/c
13492	700	N/A	7MM REM M	23-Jul-79	N	S	12-May-16	12-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512913	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13493	700	N/A	3006 SPRG	1-May-74	N	S	12-May-16	12-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	512917	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13494	700	N/A	270 WIN	9-Jan-79	N	S	12-May-16	12-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512914	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13496	700	N/A	3006 SPRG	25-Aug-76	N	S	12-May-16	12-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512915	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13497	SEVEN	29553	300 REM SA	7-Oct-02	N	S	12-May-16	12-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512868	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13498	721	N/A	3006 SPRG	1-Jun-61	Y	S	12-May-16	12-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	512919	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13503	700	N/A	3006 SPRG	14-Mar-77	N	S	16-May-16	16-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512971	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13504	SPORTSMAN 78	26172	223 REM	22-Mar-89	N	S	16-May-16	16-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512948	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13506	700	N/A	3006 SPRG	6-Oct-70	N	S	16-May-16	16-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512973	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13507	700	27478	3006 SPRG	5-Oct-98	N	S	16-May-16	17-May-16	Delayed Firing - Firearms	Could Not Duplicate Concern	512975	F	Per Iliion - Replace TA & test @ n/c
13508	700	not avail.	7MM REM M	10-Aug-70	N	S	16-May-16	17-May-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	512961	F	Per Iliion - Replace TA & test @ n/c
13509	700	not avail.	270 WIN	13-Apr-76	N	S	16-May-16	16-May-16	Fired on Safe Release	Improper Maintenance	512947	F	Per Iliion - Replace TA & test @ n/c
13511	700	25803	7MM REM M	30-Sep-86	N	S	16-May-16	24-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512974	F	Per Iliion - Replace TA & test @ n/c
13512	700	N/A	243 WIN	18-Apr-79	N	S	16-May-16	16-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512946	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge

RAC001276

Confidential

13517	700	25813	3006 SPRG	19-Apr-86	N	S	18-May-16	18-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	513011	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13518	710	27408	270 WIN	4-Jan-02	Y	S	18-May-16	18-May-16	Fired on Safe Release	Altered Adjustments or Components	513026	F	Replace w/85844 in exchange
13519	700	25711	308 WIN	30-Nov-04	N	S	18-May-16	18-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	513024	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13521	700	25711	308 WIN	21-Feb-08	N	S	18-May-16	18-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	513023	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13522	700	N/A	6MM REM	1-Jan-75	N	S	18-May-16	18-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	513044	F	Per Iliion, replace trigger, repair, check over completely, and test at no charge
13523	700	not avail.	300 WIN MA	14-Dec-81	N	S	18-May-16	19-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	513010	F	Per Iliion - Replace TA & test @ n/c
13524	700	25711	308 WIN	13-Aug-10	N	S	18-May-16	19-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	513022	F	Per Iliion - Replace TA & test @ n/c
13538	597	26536	17 HMR	20-Nov-02	N	PD/S	19-May-16	19-May-16	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	512849	F	Replace in exchange with Ramac 70723 at no charge
13549	597	26516	17 HMR	31-Jan-05	N	PD/S	23-May-16	*	My Gun Blew Up	Other - Unexamined		F	
13559	597	26514	17 HMR	15-Jun-04	N	PD/S	25-May-16	25-May-16	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	513215	F	Consumer Service is refunding purchase price
13560	597	26516	17 HMR	30-Jan-05	N	PD/S	25-May-16	25-May-16	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	512901	F	Replace in exchange with Ramac 70783 at no charge
13556	700	20000			N	PI/S	25-May-16	*	Unexplained Discharge - No Mention of Safety Position	Other - Unexamined		F	

RAC001277